



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SCN113Z

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

18991
SCN113Z / 27/08/2018
14/10/2024/ 54562
WDD2130422A475009
27492031519037
MB/MB E 200 SEDAN EXCLUSIVE/EXCLUSIVE
029 992 Selenite Gr/ 048 801 Leather Nap

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	18/10/2024/ 14:59	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M BPMSUN				
POLICY NO/ACC DATE : V5017264 // 25.06.2024				
DRIVE IN/EXCESS : 25.06.2024 // TP SH7993X- FIRST CAPITAL				
DATE IN/DATE SURVEY:				
BY/AUTHORIZED ON :				
X BASIC MOUNTING FOR BUMPER	1.00	94.05	00.00	94.05
X RIGHT REAR SHIELDING	1.00	99.14	00.00	99.14
X RIGHT TAIL PIPE COVER	1.00	493.48	00.00	493.48
X TOP BASIC MOUNTING FOR BUMPER	1.00	50.51	00.00	50.51

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

9% GST on **Nett** **737.18**
737.18 **66.35**

Authorized signatory and company stamp

Total Payable **803.53**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg