



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: AINI			Ref: CS/FCI24100112/Evp3e2(N) Date: 05/06/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 8425M	Veh. Inspected	YR 1358X
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D24006337MFCT	Excess (\$)	0.00
	Assign From	AINI	Assign Date	04/10/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150	c.c	2755
	Engine No.	HIDDEN	Year of Reg.	2023
	Chassis No.	JHHAGV4660K002896	Colour	BLACK
	Odometer	34263 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	GOODYEAR	5 mm
	L/H Front Tyre	195 R15C	GOODYEAR	5 mm
	R/H Rear Tyre	195 R15C	GOODYEAR	5 mm
	L/H Rear Tyre	195 R15C	GOODYEAR	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/07/2024	Inspection Date	18/03/2025
	Survey held at	EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD 37 LOYANG WAY, LOYANG INDUSTRIAL ESTATE, SINGAPORE 508734		
5a. Remarks				
	A) THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B) DAMAGES CONSISTENT TO ACCIDENT REPORT. C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	