

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chu, Hui Yen

Date: 07 Nov 2024

Preliminary Advice

Vehicle No	: SJY338B	Accident Date	: 05/10/2024
Make	: AUDI Q5	Policy No.	: 7230128591
Assignment Date	: 07/10/2024	Excess	: S\$500.00
Date of Inspection	: 08/10/2024	Est. Duration of Repair	: 13
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	65,399.00 (inclusive supp 2 \$11,383)
Revised Amount	:S\$	36,243.00
Check Items (Estimated)	:S\$	18,644.00
Total	:S\$	54,887.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	265,000.00
COE / PARF Rebate	:S\$	138,890.00
Salvage Value	:S\$	
Margin for Repair	:S\$	126,110.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Kindly approve supplementary-2 and 13 repair days