

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0746/2024/KS
DATE : 7-Oct-24
WIP : 33459

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 08/10/2024.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Adrian,

13 Days + 2 Sun - OK - Allan Boo

29-Nov-24

OWNER'S NAME : MR. TAN SANG THAI
ADDRESS : 96B LOR K TELOK KURAU
SINGAPORE 425730
TELEPHONE : HP +65 81387819
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7230128591
VEHICLE NO : SJY 338 B
MODEL CODE : **AUDI Q5 2.0 TFSI QU S-TRONIC**
MODEL YEAR : 27/12/2023
ENGINE NO : DMS 121062
CHASSIS NO : WAUZZZF4P2043959
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5/10/2024
PLACE OF ACCIDENT : ALONG PIE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJY 338 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. RE-INSTALL ALL PARTS REMOVED.	\$	2,400.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, BONNET AND BOTH FRONT WHEEL ARCH TRIMS.	\$	3,700.00	\$ 1,500.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$ 292.00
5A ADD LABOUR - SUPPLEMENTARY 1				\$ 3,000.00
5B ADD LABOUR - SUPPLEMENTARY 2				\$ 5,050.00
TOTAL LABOUR CHARGES		:	\$ 7,272.00	\$ 11,322.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJY 338 B.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,630.00	\$	1,304.00
2	FRONT BUMPER FIXING PARTS	1	\$ 272.00		
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 96.00		
4	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 282.00		
5	FRONT BUMPER GRILLE - CENTER	1	\$ 335.00		
6	FRONT BUMPER UNDERRUN BAR - CENTER	1	\$ 1,090.00	\$	872.00
7	FRONT BUMPER SPOILER - LH / RH	2	\$ 564.00		
8	FRONT BUMPER CLOSING ELEMENT	1	\$ 529.00		
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 598.00		
10	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 84.00		
11	FRONT PARKING AID SENSOR	2	\$ 572.00		
12	FRONT PARKING AID SENSOR SEAL RING	6	\$ 17.00		
13	RADIATOR GRILLE	1	\$ 4,178.00	\$	3,342.40
14	"QUATTRO EMBLEM	1	\$ 125.00	\$	99.60
15	RADIATOR GRILLE STRIKER PLATE	1	\$ 303.00	\$	242.40
16	"360" DEGREE CAMERA	1	\$ 1,353.00		
17	"360" DEGREE CAMERA BRACKET	1	\$ 109.00		
18	"360" DEGREE CAMERA SECURING PLATE	1	\$ 42.00		
19	"360" DEGREE CAMERA COVER CAP	1	\$ 158.00		
20	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 98.00		
SUB TOTAL SPARE PARTS		:	\$ 12,435.00	\$	5,860.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJY 338 B.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
				\$	5,860.40
21	FRONT BUMPER TOP COVER	1	\$ 162.00	\$	129.20
22	"CAUTION STICKER "	1	\$ 25.00	\$	19.44
23	"A/C" STICKER	1	\$ 25.00	\$	19.44
24	"OIL STANDARD STICKER "	1	\$ 25.00	\$	19.44
25	FRONT FOAM FILLER PIECE	1	\$ 223.00	\$	178.00
26	FRONT REINFORCEMENT BEAM	1	\$ 1,195.00	\$	956.00
27	FRONT REINFORCEMENT BEAM BRACKET - LH / RH	2	\$ 644.00		
28	RADIATOR AIR GUIDE - UPPER	1	\$ 70.00		
29	RADIATOR AIR GUIDE - CENTER	1	\$ 70.00		
30	RADIATOR AIR GUIDE - LOWER	1	\$ 70.00		
31	RADIATOR AIR GUIDE - LH / RH	2	\$ 156.00	\$	123.84
32	RADIATOR LOURVE	1	\$ 654.00	\$	523.20
33	RADIATOR LOURVE SERVOMOTOR	1	\$ 209.00		
34	LED HEADLIGHT - LH / RH	2	\$ 16,800.00		
35	LIFT CYLINDER - LH / RH	2	\$ 334.00		
36	LIFT CYLINDER HOSE - LH / RH	1	\$ 159.00		
37	LED HEADLIGHT TOP COVER - LH / RH	2	\$ 100.00	\$	78.88
38	BONNET	1	\$ 4,543.00	\$	3,634.40
39	BONNET HINGE - LH / RH	2	\$ 398.00	\$	317.60
40	BONNET ATTACHMENT PARTS	1	\$ 156.00		
SUB TOTAL SPARE PARTS		:	\$ 26,018.00	\$	11,859.84

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJY 338 B.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 11,859.84
41	BONNET STRIKER - LH / RH	2 \$	298.00	
42	BONNET IMPACT PROTECTION - LH / RH	2 \$	70.00	\$ 56.24
43	BONNET LID LOCK SWITCH	2 \$	491.00	
44	BONNET RELEASE ELEMENT	1 \$	73.00	
45	FRONT WHEEL ARCH COVER - LH / RH	2 \$	1,580.00	\$ 1,264.00
46	FRONT NO PLATE	S/N \$	60.00	\$ 60.00
	ADD PARTS - SUPPLEMENTARY 1			\$ 1,694.64
	ADD PARTS - SUPPLEMENTARY 2			\$ 5,057.44
47	SUNDRIES	\$	600.00	\$ 17.92
TOTAL SPARE PARTS			\$ 41,625.00	\$ 20,010.08
TOTAL LABOUR CHARGES			\$ 4,972.00	\$ 11,322.00
GRAND TOTAL			\$ 46,597.00	\$ 31,332.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0746/2024/KS 10-Oct-24 JOON HONG 1 of 1 SJY 338 B AUDI Q5 2.0 TFSI QU S-TRONIC
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR, CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	\$ 1,800.00	\$ 1,800.00
2	TO CARRY OUT VACUUM AND REGAS FOR R1234	\$ 1,200.00	\$ 1,200.00
<u>Parts</u>			
1	FRONT LOCK CARRIER	\$ 1,751.00	\$ 1,400.80
2	READY MIX COOLANT	\$ 332.00	\$ 265.44
3	BONNET IMPACT PROTECTION - CENTER	\$ 36.00	\$ 28.40
Parts		\$ 2,119.00	\$ 1,694.64
Labour		\$ 3,000.00	\$ 3,000.00
GRAND TOTAL		\$ 5,119.00	\$ 4,694.64

For Premium Automobiles Pte Ltd

Authorised Signature

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0746/2024/KS 4-Nov-24 GLORY 1 of 1 SJY 338 B AUDI Q5 2.0 TFSI QU S-TRONIC	
Quantity	Description		Unit Price	Amount
<u>Labours</u>				
1	TO RENEW BOTH FRONT FENDERS.		\$ 1,000.00	\$ 1,000.00
2	TO REPAIR LHS FRONT UPPER A-PILLAR.		\$ 250.00	\$ 250.00
3	TO RESPRAY BOTH FRONT FENDERS, BOTH FRONT DOORS AND BOTH UPPER A-PILLARS.		\$ 3,300.00	\$ 3,300.00
4	TO REMOVE AND REINSTALL BOTH FRONT WING MIRROR ASSY TO RESPRAY BOTH FRONT DOORS.	S/N	\$ 500.00	\$ 500.00
<u>Parts</u>				
1	HEADLIGHT MOUNTING RHS/LHS	2	\$ 294.00	\$ 235.20
2	FRONT FENDER RHS/LHS	2	\$ 3,658.00	\$ 2,926.40
3	FRONT FENDER BRACE RHS/LHS	2	\$ 532.00	\$ 424.80
4	OUTER TEMPERATURE SENSOR BRACKET		\$ 27.00	\$ 15.84
5	FRONT DOOR WINDOW SLOT SEAL RHS/LHS	2	\$ 1,548.00	\$ 1,237.60
6	FRONT FENDER TOP LEDGE COVER OUTER RHS/LHS	2	\$ 196.00	\$ 155.52
7	FRONT FENDER TOP LEDGE COVER INNER RHS/LHS	2	\$ 78.00	\$ 62.08
		Parts	\$ 6,333.00	\$ 5,057.44
		Labour	\$ 5,050.00	\$ 5,050.00
GRAND TOTAL			\$ 11,383.00	\$ 10,107.44

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT