

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0746/2024/KS
DATE : 7-Oct-24
WIP : 33459

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 08/10/2024.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR. TAN SANG THAI
ADDRESS : 96B LOR K TELOK KURAU
SINGAPORE 425730
TELEPHONE : HP +65 81387819
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7230128591
VEHICLE NO : SJY 338 B
MODEL CODE : **AUDI Q5 2.0 TFSI QU S-TRONIC**
MODEL YEAR : 27/12/2023
ENGINE NO : DMS 121062
CHASSIS NO : WAUZZZFY4P2043959
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5/10/2024
PLACE OF ACCIDENT : ALONG PIE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJY 338 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	?
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. RE-INSTALL ALL PARTS REMOVED.	\$	2,400.00	1000 ✓
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, BONNET AND BOTH FRONT WHEEL ARCH TRIMS.	\$	3,700.00	1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	✓
TOTAL LABOUR CHARGES		:	\$ 7,272.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJY 338 B.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>rebuild</i>	1	\$ 1,630.00	✓	
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 272.00	+	
3	FRONT BUMPER SECURING STRIP - LH / RH <i>new</i>	2	\$ 96.00	+	
4	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2	\$ 282.00	+	
5	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 335.00	+	
6	FRONT BUMPER UNDERRUN BAR - CENTER <i>new</i>	1	\$ 1,090.00	+	
7	FRONT BUMPER SPOILER - LH / RH <i>new</i>	2	\$ 564.00	+	
8	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 529.00	+	
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 598.00	+	
10	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>new</i>	2	\$ 84.00	+	
11	FRONT PARKING AID SENSOR <i>new</i>	2	\$ 572.00	+	
12	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	6	\$ 17.00	+	
13	RADIATOR GRILLE <i>new</i>	1	\$ 4,178.00	✓	
14	"QUATTRO EMBLEM <i>new</i>	1	\$ 125.00	✓	
15	RADIATOR GRILLE STRIKER PLATE ?	1	\$ 303.00	?	
16	"360" DEGREE CAMERA <i>new</i>	1	\$ 1,353.00	+	
17	"360" DEGREE CAMERA BRACKET <i>new</i>	1	\$ 109.00	+	
18	"360" DEGREE CAMERA SECURING PLATE ?	1	\$ 42.00	?	
19	"360" DEGREE CAMERA COVER CAP ?	1	\$ 158.00	?	
20	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 98.00	+	
SUB TOTAL SPARE PARTS		:	\$ 12,435.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJY 338 B.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER TOP COVER <i>cracked</i>	1	\$ 162.00	<i>✓</i>
22	"CAUTION STICKER "	1	\$ 25.00	<i>✓</i>
23	"A/C" STICKER <i>new</i>	1	\$ 25.00	<i>✓</i>
24	"OIL STANDARD STICKER "	1	\$ 25.00	<i>✓</i>
25	FRONT FOAM FILLER PIECE <i>?</i>	1	\$ 223.00	<i>?</i>
26	FRONT REINFORCEMENT BEAM <i>?</i>	1	\$ 1,195.00	<i>?</i>
27	FRONT REINFORCEMENT BEAM BRACKET - LH / RH <i>?</i>	2	\$ 644.00	<i>?</i>
28	RADIATOR AIR GUIDE - UPPER <i>?</i>	1	\$ 70.00	<i>+</i>
29	RADIATOR AIR GUIDE - CENTER <i>new</i>	1	\$ 70.00	<i>+</i>
30	RADIATOR AIR GUIDE - LOWER <i>new</i>	1	\$ 70.00	<i>+</i>
31	RADIATOR AIR GUIDE - LH / RH <i>new</i>	2	\$ 156.00	<i>+</i>
32	RADIATOR LOURVE <i>new</i>	1	\$ 654.00	<i>+</i>
33	RADIATOR LOURVE SERVOMOTOR <i>new</i>	1	\$ 209.00	<i>+</i>
34	LED HEADLIGHT - LH / RH <i>?</i>	2	\$ 16,800.00	<i>?</i>
35	LIFT CYLINDER - LH / RH <i>new</i>	2	\$ 334.00	<i>+</i>
36	LIFT CYLINDER HOSE - LH / RH <i>new</i>	1	\$ 159.00	<i>+</i>
37	LED HEADLIGHT TOP COVER - LH / RH <i>new</i>	2	\$ 100.00	<i>+</i>
38	BONNET <i>Dented</i>	1	\$ 4,543.00	<i>✓</i>
39	BONNET HINGE - LH / RH <i>new</i>	2	\$ 398.00	<i>+</i>
40	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 156.00	<i>+</i>
SUB TOTAL SPARE PARTS		:	\$	26,018.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJY 338 B.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	BONNET STRIKER - LH / RH <i>nee m</i>	2	\$ 298.00	+	
42	BONNET IMPACT PROTECTION - LH / RH <i>nee</i>	2	\$ 70.00	✓	
43	BONNET LID LOCK SWITCH <i>nee m</i>	2	\$ 491.00	+	
44	BONNET RELEASE ELEMENT <i>nee m</i>	1	\$ 73.00	+	
45	FRONT WHEEL ARCH COVER - LH / RH <i>nee</i>	2	\$ 1,580.00	✓	
46	FRONT NO PLATE <i>Deited</i>	S/N	\$ 60.00	✓	
47	SUNDRIES <i>?</i>		\$ 600.00	?	
TOTAL SPARE PARTS		:	\$ 41,625.00		
TOTAL LABOUR CHARGES		:	\$ 4,972.00		
GRAND TOTAL		:	\$ 46,597.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian Lij
08/10/24

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 04 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT