

ASS. REC. BY:

REF:

AGZ CS/AGI24060201/Kvh3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SFB 777K

Policy No.

Claims No. C10030084/ML

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

: Prel. Report

: Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fines

Others

TOTAL

Add Fee:

: Site Insp (\$

: Interview (\$

Tech Invs (\$

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

1/ E9 not ready

3/7 L1Ry 82000/- Cabul (red 11,226, 84%)

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: HYUNDAI KONA

Engine/Chassis No.: KMHK281EVNU089167

Date of accident: 20.07.24

Damaged area: O/S

Date: 25/06/2024

Claim Type: TP

VRN: SNE7119D

*Not Authorised
L/Ry @ 2000h
Penny After Pain
3 days*

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front door o/s	R 1	\$ 1,915.00	\$ 1,915.00
2	Front door hinge o/s	R 2	\$ 135.00	\$ 270.00
3	Front door lower moulding o/s <i>301.80</i>	L 1	\$ 435.00	\$ 435.00
4	Front door checker o/s	R 1	\$ 65.00	\$ 65.00
5	Front door window outer channel o/s	R 1	\$ 89.00	\$ 89.00
6	Front door outer handle o/s	R 1	\$ 253.00	\$ 253.00
7	Front door lock o/s	R 1	\$ 267.00	\$ 267.00
8	Front door lock sensor o/s	R 1	\$ 629.00	\$ 629.00
9	B pillar o/s	R 1	\$ 1,185.00	\$ 1,185.00
10	Rear door o/s	R 1	\$ 1,854.00	\$ 1,854.00
11	Rear door side moulding o/s	R 1	\$ 253.00	\$ 253.00
12	Rear door hinge o/s	R 2	\$ 135.00	\$ 270.00
13	Rear door lower moulding o/s <i>245.60</i>	L 1	\$ 365.00	\$ 365.00
14	Rear door checker o/s	R 1	\$ 85.00	\$ 85.00
15	Rear door outer handle o/s	R 1	\$ 252.00	\$ 252.00
16	Rear fender arch garnish o/s <i>235.20</i>	L 1	\$ 435.00	\$ 435.00
17	Rocker panel moulding o/s <i>401.80</i>	L 1	\$ 836.00	\$ 836.00
18	Rear bumper <i>628.40</i>	L 1	\$ 1,286.00	\$ 1,286.00
19	Rear bumper side retainer	R 2	\$ 113.00	\$ 226.00
Subtotal				\$ 10,970.00
List discount				20.00%
Total				\$ 8,776.00

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Sundries	N 1	\$ 50.00	\$ 50.00
2	Rear door inner trim board clips o/s	N 10	\$ 5.50	\$ 55.00
3	Front door inner trim board clips o/s	N 10	\$ 5.50	\$ 55.00
4	Rear fender arch garnish clips o/s	N 8	\$ 5.50	\$ 44.00
5	Rear bumper clips	N 12	\$ 5.50	\$ 66.00
6	Rear alloy wheel o/s <i>L.P. 1</i>	1	\$ 650.00	\$ 650.00
7	Rear tyre o/s	R 1	\$ 280.00	\$ 280.00
Total				\$ 1,200.00

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	8	\$ 1,600.00
2	To disconnect doors wire harness of electrical component to facilitate repairs, reconnect and check functions of power windows.	0.25	\$ 50.00
3	To remove and refit o/s front & rear door components to replace o/s front & rear door, check alignment.	0.5	\$ ~ 100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	7	\$ 1,400.00
5	To rust proof all affected portions after repair.	0.5	\$ ~ 100.00
Total labour			\$ 3,250.00

500/

15/

X

440/

X

Estimate Grand Total		\$	13,226.00
----------------------	--	----	-----------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: