

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Xiao Chen.

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6111
 Fax : 6224 - 7478 / 7175

Quotation
 DATE : 08.10.2024
 VEH NO : SNA5576B
 MODEL : Hyundai i30
 D O A : 19.09.2024
 YR REF : SMP5173M

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SNA5576B (HYUNDAI i30)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Rear Bumper <i>Delnd</i>	1	985.40 ✓
2	Rear Bumper Side Holder <i>new</i>	1	40.40 ✗
3	Rear Bumper Lower Garnish <i>Delnd</i>	1	406.60 ✓
4	Rear Bumper Reflector <i>ut</i>	1	248.60 ✓
5	Rear Bumper Reinforcement <i>Rein</i>	1	435.90 ✗
6	Rear Bumper Reinforcement Stay <i>Not new</i>	1	178.20 ✗
7	Rear Bumper Sensor <i>1 piece damaged</i>	2	420.20 210.10
8	Rear Bumper Sensor Holder <i>new</i>	2	40.20 ✓
9	Rear Bumper Towing Cover <i>new</i>	1	28.40 ✗
10	Rear End Panel <i>? Not new</i>	1	1,321.10 ✗
11	Rear End Panel Top Garnish	1	225.40 ✗
12	Rear End Panel Antenna Sensor	1	120.90 ✗
13	Taillamp <i>Not new</i>	1	1,258.20 ✗
14	Tailgate <i>Dented</i>	1	2,295.40 ✓
15	Tailgate Lock <i>Not new</i>	1	229.40 ✗
16	Tailgate Weatherstripe <i>Not new</i>	1	289.50 ✗
17	Tailgate Inner Trim Board <i>Not new</i>	1	445.90 ✗
18	Tailgate Lamp <i>Not new</i>	2	795.40 ✗
19	Tailgate Glass Moulding <i>new</i>	1	180.10 ✓
20	Hyundai Logo <i>? new</i>	1	75.10 ✓
21	i30 Emblem	1	74.90 ✓
22	Spare Tyre Panel Top Board <i>? Not new</i>	1	456.10 ✗
23	Rear Fender Inner Trim Board <i>? new</i>	1	570.90 ✗
			\$ 11,122.20
Less 20%			\$ (2,224.44)
			\$ 8,897.76

S/NETT ITEMS

RE : ESTIMATE FOR ACCIDENT REPAIR SNA5576B (HYUNDAI i30)

1	Rear Bumper Clips <i>new</i>	1 set	30.00	✓
2	Rear End Panel Top Garnish Clips	1 set	20.00	+
3	Rear End Panel Sealant	1 set	60.00	+
4	Tailgate Inner Trim Board Clips <i>new</i>	1 set	30.00	+
5	Tailgate Glass Sealant <i>new</i>	1 set	60.00	✓
6	Rear Fender Inner Trim Board Clips <i>new</i>	1 set	30.00	+

230.00

Total parts

\$ 9,127.76

LABOUR CHARGE

1	To knocking out rear portion & renew above parts	\$	1,200.00	400
2	To putty & spray up paint works	\$	1,000.00	400
3	To check wiring	\$	50.00	30
4	To apply tuff coat	\$	150.00	X
5	To remove reverse sensor	\$	100.00	50
6	To remove rear camera	\$	100.00	50
7	To remove upholstery	\$	150.00	X
8	To transfer tailgate fittings	\$	150.00	80
9	To remove tailgate glass	\$	180.00	120

Total Labour

\$ 3,080.00

Grand Total

\$ 12,207.76

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4833.12
h/s: 3850
04 Days.