

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CD/A16 2410012/Uua3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SM C 9906H

at Workshop m/s

Symphony 7

of

Insured:

SAF 28789

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value:

\$63k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

151 b

Date:

Person Contacted:

Vehicle: IN / OUT

L7A 32903

Date / Time

Action / Instruction

D9p 13k

have accident scene photo of folder
15/10/24 4/5 \$7100 in hand Jason

Veh No:

SMC9906H

rr Regn:

30/07/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CAI

Make:

VOLVO

S60

c.c

1969

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

107054

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

YV1FS 40LDJ 2468728

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/50ZR17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC POHTSU / PIR / SUMI / TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

05/10/24

D.O.I.

08/10/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SMC9906H

MAKE & MODEL: VOLVO S60 T5

Not Authorized
Mr
Mora's
8/10/24
2/5 #7102/
H day's
Take photo after repair

BOOTLID	DD/Bent	2450	\$2,556.10	✓
BOOTLID LOGO	VOLVO emblem	110	\$138.30	✓
BOOTLID S60 EMBLEM	all	70	\$78.40	✓
BOOTLID T5 EMBLEM	all	60	\$64.10	✓
BOOTLID LAMP L/R X2	11		\$956.60	X
BOOTLID HINGE L/R X2	11		\$412.60	X
BOOTLID INNER LOCK	all		\$616.20	X
BOOTLID LOCK STRIKER	11		\$78.00	X
BOOTLID WEATHERSTRIP	11		\$616.20	X
REAR CAMERA	11		\$1,562.30	X
TAIL LAMP L/R X2	M/S 11 0/5 cre	825	\$2,322.40	1PC
TAIL LAMP BRACKET L/R X2	M/S 11 0/5 cre	105	\$278.60	1PC
TAIL LAMP INNER PANEL L/R X2	11		\$386.40	X
REAR BUMPER	Dis	1845	\$1,984.20	✓
REAR BUMPER LOWER	Dis	780	\$941.10	✓
REAR BUMPER SIDE RETAINER L/R X2	C/A	145 x 2 = 290	\$312.20	✓
REAR BUMPER CENTRE BRACKET	NF		\$296.00	X
REAR BUMPER REVERSE SENSOR L/R X2	0/5 cre	245	\$598.60	1PC
REAR BUMPER REVERSE SENSOR BRACKET SET	all		\$156.00	✓
REAR BUMPER TOW COVER	Torn	48	\$76.30	✓
REAR BUMPER REINFORCEMENT	DD/Bent		\$823.40	✓
END PANEL	2		\$1,521.10	X
END PANEL GARNISH	11		\$368.70	X
REAR FENDER RH	2		\$2,414.20	X
REAR FENDER INNER TRIM RH	11		\$517.40	X
REAR FENDER LH	11		\$2,414.20	X
REAR FENDER INNER TRIM LH	11		\$517.40	X
REAR FENDER SPLASH SHIELD L/R X2	11		\$552.40	X
SPARE TYRE PANEL TOP BOARD	11		\$511.60	X
SPARE TYRE PANEL	2		\$1,145.60	X
REAR EXHAUST RH	2		\$891.40	X
REAR EXHAUST CHROME TRIM RH	Bent		\$311.20	✓
REAR EXHAUST HEAT SHIELD RH	11		\$298.70	X
REAR sensor wire	Torn		\$234.50	✓
			\$26,952.40	
		Less 10%	\$2,695.24	
			\$24,257.16	

124	REAR BUMPER CLIPS	all	\$60.00	30 s/10
	REAR BOOTLID INNER TRIM CLIPS	11	\$50.00	X
	REAR NUMBER PLATE WITH GARNISH	11	\$70.00	X

END PANEL GARNISH CLIPS	^^	\$60.00	x
END PANEL SEALANT	^^	\$100.00	x
SPARE TYRE PANEL SEALANT	^^	\$100.00	x
REAR FENDER INNER TRIM CLIPS RH	^^	\$60.00	x
REAR FENDER SEALANT RH	^^	\$80.00	x
REAR FENDER INNER TRIM CLIPS LH	^^	\$60.00	x
REAR FENDER SEALANT LH	^^	\$80.00	x
REAR WINDSCREEN SEALANT	^^	\$80.00	x
REAR WINDSCREEN SPONGE	^^	\$60.00	x
		\$860.00	

TO CHECK REAR WIRING		\$50.00	20
TO REPLACE REAR REVERSE SENSOR		\$80.00	30
TO REMOVE AND REFIT REAR REVERSE CAMERA	^^	\$100.00	x
TO REMOVE AND TRANSFER BOOTLID FITTINGS TO NEW		\$100.00	50
TO REMOVE AND REFIT REAR INTERIOR TRIMS		\$160.00	60
TO REMOVE AND REPLACE REAR EXHAUST MUFFLER	^^	\$280.00	x
TO REMOVE AND REFIT REAR WINDSCREEN	^^	\$180.00	x
TO PROVIDE LABOUR, WORKMANSHIP		\$2,400.00	550
TO SPRAY PAINT ON AFFECTED PANELS		\$2,000.00	700
TO CONDUCT COMPUTERISE DIAGNOSTIC RESET	^^	\$350.00	x
RUST PROOFING		\$150.00	30
		\$5,850.00	

Total

\$30,967.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 8353-1
102
7517.79
30
1440
8987.79
202