

Yew Tee Automobile Tech Pte Ltd

39 Woodlands Close #01-12, Mega@Woodlands

Singapore 737856

Tel: 62562081 Email: info@yewteegroup.com

(SUPPLEMENTARY)

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC23A00335301	Date of Loss:	21/09/2024
Vehicle Reg. No.:	SMF5384Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SYED FESHAL BIN S ABDULRAB TALIB		
Driver:	SYED FESHAL BIN S ABDULRAB TALIB		

Make/Model:	TOYOTA SIENTA, 1.5 (A)	Vehicle Reg. Date:	16/11/2018
Vehicle Colour:	BROWN		
Engine No:	2NRX397895	Chassis No:	MHFZ28H3300059966
Odometer:	53505 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	15

Present Location:	YEW TEE AUTOMOBILE TECH PTE LTD (WOODLANDS)
-------------------	---

COST OF CLAIMS

	Amount
Parts	2,288.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,288.00
+ GST 9.00% (S\$)	205.92
Nett Amount (S\$)	2,493.92
+ Previous Estimates (S\$)	14,692.33
Claim Total (S\$)	17,186.25

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 14 Oct 2024)

Parts: M1-MPV

TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Yew Tee Automobile Tech Pte Ltd/SMF5384Z/14/10/2024 11:27

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR FENDER INNER GARNISH RH <i>Defend</i>	0.00	0.00	*250.00 F <i>250</i>
2	1		*REAR SPARE TYRE TOP BOX <i>Defend</i>	0.00	0.00	*120.00 F <i>120</i>
3	1		*RACK END PANEL <i>Repaired Perked</i>	0.00	0.00	*220.00 F <i>180</i>
4	1		*REAR EXHAUST PIPE <i>Defend</i>	0.00	0.00	*1,300.00 F <i>600</i>
5	1		*REAR BOOT TRIM <i>Repaired</i>	0.00	0.00	*80.00 F
6	1		*REAR END PANEL TOP BOARD <i>Defend</i>	0.00	0.00	*110.00 F <i>X</i>

F=Franchise part.

Sub Total (S\$)	2,080.00
+ Margin on L,N Items 10.00% (S\$)	208.00
Total Parts (S\$)	2,288.00

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/14/10/2024 11:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Admin G
Slip

9743 2262
Shawn

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/14/10/2024 11:27. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >