

REF:

CS/ICS24100122/Avh3

ASSIGNMENT

Front: _____ Date: _____

Estimate: _____

OD / TP RES / CD RES / EVA / INV / MV

To in Vehicle NO: 97432262

at Work: 65921522

of _____

Insured: _____

Policy No. MPC23A00335301

Claim No. DMPC2401321H/ST

Sum Insured: _____ Excess: 0

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMFS3842 Yr Regn: 2018 / Nov

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Sienta C.D. 1496

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 53505 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MHF228H3300059966

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/50R16

R: 185/50R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GT.

Front Rear

R/Bal. 86 mm R/Bal. 86 mm

L/Bal. 96 mm L/Bal. 96 mm

D.O.A. 21/9/24 D.O.I. 07/10/24

Survey held at Yew Tee

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OO ECICS

19/12/24 Final fig \$5790 confirmed by email (Red 9977.20, 63%)

COE Expiry

Estimate given during: Yes

1st Survey: No

MV: 66K

PV: 262K

Nett: 39.8K

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: _____

Addl Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Insp (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS: \$1

Photos

Others

Report Format: _____

Report Format: _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	01/10/2024 13:47 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	21/09/2024 11:30 (SGT)
Exact Location of Accident	Malaysia
Additional Location Information	KM3 PASIR GUDANG PERLING
Country/State of Loss	Malaysia

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF5384Z
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	SYED FESHAL BIN S ABDULRAB TALIB
NRIC No	SXXXX827A
Email Address	FESHALTALIB@HOTMAIL.COM
Mobile Phone No	(Phone) +65-98298516
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Sienta
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	0
Vehicle Fuel	Petrol
First Registration Date	16/11/2018
Chassis no	MHFZ28H3300059966
Effective Date/Time of Ownership	16/11/2018 00:00 (SGT)

INSURANCE COMPANY

Name of Insurance Company	ECICS Limited
Policy Number / Cover Note Number	MPC23A00335301

DRIVER

Name of Driver	SYED FESHAL BIN S ABDULRAB TALIB
NRIC No	SXXXX827A
Date Of Birth	07/08/1956
Occupation	Indoor
Driving Pass Date	28/12/1979
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	44 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98298516
Alt. Phone Number	-
Email Address	FESHALTALIB@HOTMAIL.COM
Address	55 NEW UPPER CHANGI ROAD #14-1458
Address complement	-
Postcode	461055
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	Yes
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

FOREIGN VEHICLE 1

Vehicle Registration Number	JUF9451
Vehicle Category	Motorcycle

PASSENGER 1

Name	UNKNOWN
Gender	Female

PASSENGER 2

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	TRAFIK JOHOR BAHRU
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	VIDEO WITH OWNER

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JUF9451
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Motorcycle
Name of Driver	MOHAMAD FARUL RAFIQ BIN ROHAIZAD
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	MOHAMAD FARUL RAFIQ BIN ROHAIZAD
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	JUF9451
Were seat belts worn?	No
Was this injured conveyed to hospital by ambulance?	Yes

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Actual Driver's Signature (If driver is not the policyholder) / Date & Time

LENG
Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



A = SMIF 53842
B = JUF 7151

Diagram of a vehicle with points A and B marked.

vJun2022

1

Describe Circumstance of the Accident

On 21/09/2024 at about 11:30 AM, when I was driving my vehicle A (SMF 5384Z) from PASIR GUDANG TOWARDS JOHOR BAHRU, MALAYSIA.

When I reach kilometre 3 PASIR GUDANG I filter to the left most lane due to my car ~~get~~ got warning light blinking, then I on my hazard light at the left most lane not even 1 minutes and 30 seconds only, I felt an big impact from my rear portion which was bang by the vehicle B (JVF 9451).

Declaration

I/We declare the foregoing particulars are true in every respect.

 Policyholder's Signature / Date & Time	 Actual Driver's Signature (if driver is not the policyholder) / Date & Time	LENG Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)
---	--	---

Yew Tee Automobile Tech Pte Ltd39 Woodlands Close #01-12, Mega@Woodlands
Singapore 737856

Tel: 62562081 Email: info@yewteegroup.com

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC23A00335301	Date of Loss:	21/09/2024
Vehicle Reg. No.:	SMF5384Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SYED FESHAL BIN S ABDULRAB TALIB		
Driver:	SYED FESHAL BIN S ABDULRAB TALIB		
Make/Model:	TOYOTA SIENTA, 1.5 (A)	Vehicle Reg. Date:	16/11/2018
Vehicle Colour:	BROWN	Chassis No:	MHFZ28H3300059966
Engine No:	2NRX397895		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Present Location:	YEW TEE AUTOMOBILE TECH PTE LTD (WOODLANDS)		

COST OF CLAIMS	Amount
Parts	8,670.20
Miscellaneous Items	259.00
Labour	4,550.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	13,479.20
+ GST 9.00% (\$\$)	1,213.13
Nett Amount (\$\$)	14,692.33

This claim is handled by: TOH TZE CHANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2024)
Parts: M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: Yew Tee Automobile Tech Pte Ltd/SMF5384Z/04/10/2024 14:39	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>Deband</i>	0.00	0.00	*480.00 F <i>160</i>
2	1		*REAR BUMPER SIDE RETAINER LH <i>and</i>	0.00	0.00	*80.00 F <i>+50</i>
3	1		*REAR BUMPER SIDE RETAINER RH <i>and</i>	0.00	0.00	*80.00 F <i>+50</i>
4	1		*REAR BUMPER BRACKET LH <i>3 new</i>	0.00	0.00	*65.00 F <i>+40</i>
5	1		*REAR BUMPER BRACKET RH <i>and</i>	0.00	0.00	*65.00 F <i>+70</i>
6	1		*REAR BUMPER TOP GARNISH (BLACK) <i>Deband</i>	0.00	0.00	*130.00 F <i>+40</i>
7	1		*REAR BUMPER SIDE TOP GARNISH LH (BLACK) <i>new</i>	0.00	0.00	*170.00 F <i>+35</i>
8	1		*REAR BUMPER SIDE TOP GARNISH RH (BLACK) <i>Deband</i>	0.00	0.00	*170.00 F <i>+480</i>
9	1		*REAR BUMPER SIDE TOP GARNISH LH (BLACK) REFLECTOR <i>new</i>	0.00	0.00	*90.00 F <i>+150</i>
10	1		*REAR BUMPER SIDE TOP GARNISH RH (BLACK) REFLECTOR <i>cracked</i>	0.00	0.00	*90.00 F <i>+70</i>
11	1		*REAR TAILGATE <i>Distorted</i>	0.00	0.00	*780.00 F <i>+150</i>
12	1		*REAR TAILGATE RUBBER <i>new</i>	0.00	0.00	*230.00 F <i>+70</i>
13	1		*REAR TAILGATE LOCK <i>new</i>	0.00	0.00	*320.00 F <i>+40</i>
14	1		*REAR TAILGATE LOCK CATCH <i>Deband</i>	0.00	0.00	*56.00 F <i>+45</i>
15	1		*REAR TAILGATE INNER BOARD <i>new</i>	0.00	0.00	*130.00 F <i>+45</i>
16	1		*REAR TAILGATE INNER BOARD HANDLE <i>new</i>	0.00	0.00	*56.00 F <i>+45</i>
17	1		*REAR TAILGATE HINGES LH <i>Bent</i>	0.00	0.00	*75.00 F <i>+45</i>
18	1		*REAR TAILGATE HINGES RH <i>Bent</i>	0.00	0.00	*75.00 F <i>+45</i>
19	1		*REAR TAILGATE DAMPER LH <i>new</i>	0.00	0.00	*160.00 F <i>+45</i>
20	1		*REAR TAILGATE DAMPER RH <i>new</i>	0.00	0.00	*160.00 F <i>+45</i>
21	1		*REAR TAILGATE LOGO <i>Not</i>	0.00	0.00	*48.00 F <i>+45</i>
22	1		*REAR TAILGATE SIENTA EMBLEM <i>new</i>	0.00	0.00	*48.00 F <i>+45</i>
23	1		*REAR TAILGATE HYBRID EMBLEM <i>new</i>	0.00	0.00	*64.00 F <i>+45</i>
24	1		*REAR TAILGATE REFLECTOR LH <i>new</i>	0.00	0.00	*440.00 F <i>+160</i>
25	1		*REAR TAILGATE REFLECTOR RH <i>cracked</i>	0.00	0.00	*440.00 F <i>+160</i>
26	1		*REAR TAILGATE OUTER CHROME <i>new</i>	0.00	0.00	*320.00 F <i>+160</i>
27	1		*REAR NUMBER PLATE LAMP LH <i>Not</i>	0.00	0.00	*70.00 F <i>+300</i>
28	1		*REAR NUMBER PLATE LAMP RH <i>new</i>	0.00	0.00	*70.00 F <i>+300</i>
29	1		*REAR WINDSCREEN GLASS <i>Shattered</i>	0.00	0.00	*480.00 F <i>+170</i>
30	1		*REAR TAILLAMP LH <i>new</i>	0.00	0.00	*350.00 F <i>+80</i>
31	1		*REAR TAILLAMP RH <i>Missing</i>	0.00	0.00	*350.00 F <i>+55</i>
32	1		*REAR TAILLAMP PANEL RH <i>Revised</i>	0.00	0.00	*210.00 F <i>+45</i>
33	1		*REAR TAILLAMP LOWER BRACKET RH <i>new</i>	0.00	0.00	*60.00 F <i>+200</i>
34	1		*REAR FENDER TOP RH <i>Cracked</i>	0.00	0.00	*480.00 F <i>+90</i>
35	1		*REAR FENDER LOWER RH <i>new</i>	0.00	0.00	*560.00 F <i>+90</i>
36	1		*REAR END PANEL <i>Dented</i>	0.00	0.00	*290.00 F <i>+90</i>
37	1		*REAR END PANEL INNER GARNISH <i>Cracked</i>	0.00	0.00	*140.00 F <i>+90</i>

F=Franchise part.

Sub Total (\$)
+ Margin on L,N Items 10.00% (\$)

7,882.00
788.20

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/04/10/2024 14:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

10/7/24, 2:19 PM

Repairer Estimates

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						8,670.20

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/04/10/2024 14:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	REAR BUMPER SENSOR (SET) <i>standard.</i>	200.00 <i>+ 200</i>
2	1	REAR NUMBER PLATE <i>new</i>	35.00 <i>+</i>
3	1	REAR WINDSCREEN SEALANT <i>new</i>	24.00 <i>✓</i>
Sub Total (S\$)			259.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO ELECTRICAL WIRING SERVICES	New	30.00 <i>✓</i>
2	TO DISMANTLE & REFIT REAR SENSORS	New	60.00 <i>50</i>
3	TO DISMANTLE & REFIT REAR WINDSCREEN GLASS	New	100.00 <i>✓</i>
4	TO REMOVE, REFIX, REALIGN, ADJUST AND REPLACE ALL DAMAGED PARTS	New	2,800.00 <i>800</i>
5	TO UNDERCOATING FOR RUST PROTECTION	New	60.00 <i>40</i>
6	TO SPRAY PAINTING ACCIDENT PORTION	New	1,500.00 <i>800</i>
Gross Labour Cost (S\$)			4,550.00

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/04/10/2024 14:39. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim
P/P 07/06/24

Not Authorised

Excess: To be advised

06 Days.

Yew Tee Automobile Tech Pte Ltd

39 Woodlands Close #01-12, Mega@Woodlands

Singapore 737856

Tel: 62562081 Email: info@yewteegroup.com

(SUPPLEMENTARY)

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC23A00335301	Date of Loss:	21/09/2024
Vehicle Reg. No.:	SMF5384Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SYED FESHAL BIN S ABDULRAB TALIB		
Driver:	SYED FESHAL BIN S ABDULRAB TALIB		

Make/Model:	TOYOTA SIENTA, 1.5 (A)	Vehicle Reg. Date:	16/11/2018
Vehicle Colour:	BROWN		
Engine No:	2NRX397895	Chassis No:	MHFZ28H3300059966
Odometer:	53505 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	15

Present Location:	YEW TEE AUTOMOBILE TECH PTE LTD (WOODLANDS)
-------------------	---

COST OF CLAIMS

	Amount
Parts	2,288.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,288.00
+ GST 9.00% (S\$)	205.92
Nett Amount (S\$)	2,493.92
+ Previous Estimates (S\$)	14,692.33
Claim Total (S\$)	17,186.25

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 14 Oct 2024)**Parts:** M1-MPV TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Yew Tee Automobile Tech Pte Ltd/SMF5384Z/14/10/2024 11:27**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR FENDER INNER GARNISH RH <i>Defend</i>	0.00	0.00	✓ *250.00 F
2	1		*REAR SPARE TYRE TOP BOX <i>Defend</i>	0.00	0.00	✓ *120.00 F
3	1		*RACK END PANEL <i>Repeated</i>	0.00	0.00	+ *220.00 F
4	1		*REAR EXHAUST PIPE <i>Dented</i>	0.00	0.00	✓ *1,300.00 F
5	1		*REAR BOOT TRIM <i>Repeated</i>	0.00	0.00	+ *80.00 F
6	1		*REAR END PANEL TOP BOARD <i>Defend</i>	0.00	0.00	✓ *110.00 F

F=Franchise part.

Sub Total (\$\$)	2,080.00
+ Margin on L,N Items 10.00% (\$\$)	208.00
Total Parts (\$\$)	2,288.00

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/14/10/2024 11:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Adrian G
S.P.

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/14/10/2024 11:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Yew Tee Automobile Tech Pte Ltd

39 Woodlands Close #01-12, Mega@Woodlands

Singapore 737856

Tel: 62562081 Email: info@yewteegroup.com

(SUPPLEMENTARY)

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC23A00335301	Date of Loss:	21/09/2024
Vehicle Reg. No.:	SMF5384Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SYED FESHAL BIN S ABDULRAB TALIB		
Driver:	SYED FESHAL BIN S ABDULRAB TALIB		

Make/Model:	TOYOTA SIENTA, 1.5 (A)	Vehicle Reg. Date:	16/11/2018
Vehicle Colour:	BROWN	Chassis No:	MHFZ28H3300059966
Engine No:	2NRX397895		
Odometer:	53505 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		

Present Location: **YEW TEE AUTOMOBILE TECH PTE LTD (WOODLANDS)**

COST OF CLAIMS

	Amount
Parts	2,288.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,288.00
+ GST 9.00% (S\$)	205.92
Nett Amount (S\$)	2,493.92
+ Previous Estimates (S\$)	14,692.33
Claim Total (S\$)	17,186.25

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 14 Oct 2024)

Parts: M1-MPV **TOYOTA SIENTA 1.5 (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Yew Tee Automobile Tech Pte Ltd/SMF5384Z/14/10/2024 11:27

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR FENDER INNER GARNISH RH <i>Deformed</i>	0.00	0.00	✓ *250.00 F <i>250</i>
2	1		*REAR SPARE TYRE TOP BOX <i>Deformed</i>	0.00	0.00	✓ *120.00 F <i>120</i>
3	1		*RACK END PANEL <i>Replaced Perforated</i>	0.00	0.00	✓ *220.00 F <i>180</i>
4	1		*REAR EXHAUST PIPE <i>Dented</i>	0.00	0.00	✓ *1,300.00 F <i>600</i>
5	1		*REAR BOOT TRIM <i>Replaced</i>	0.00	0.00	X *80.00 F
6	1		*REAR END PANEL TOP BOARD <i>Deformed</i>	0.00	0.00	✓ *110.00 F X

F=Franchise part.

Sub Total (\$\$)	2,080.00
+ Margin on L,N Items 10.00% (\$\$)	208.00
Total Parts (\$\$)	2,288.00

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/14/10/2024 11:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Adam G
S.S.

9743 2262

Sham

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/14/10/2024 11:27. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >