

Yew Tee Automobile Tech Pte Ltd39 Woodlands Close #01-12, Mega@Woodlands
Singapore 737856

Tel: 62562081 Email: info@yewteegroup.com

(SUPPLEMENTARY)

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC23A00335301	Date of Loss:	21/09/2024
Vehicle Reg. No.:	SMF5384Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SYED FESHAL BIN S ABDULRAB TALIB		
Driver:	SYED FESHAL BIN S ABDULRAB TALIB		
Make/Model:	TOYOTA SIENTA, 1.5 (A)	Vehicle Reg. Date:	16/11/2018
Vehicle Colour:	BROWN	Chassis No:	MHFZ28H3300059966
Engine No:	2NRX397895		
Odometer:	53505 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Present Location:	YEW TEE AUTOMOBILE TECH PTE LTD (WOODLANDS)		

COST OF CLAIMS	Amount
Parts	2,288.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,288.00
+ GST 9.00% (\$\$)	205.92
Nett Amount (\$\$)	2,493.92
+ Previous Estimates (\$\$)	14,692.33
Claim Total (\$\$)	17,186.25

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Oct 2024)**Parts:** M1-MPV TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Yew Tee Automobile Tech Pte Ltd/SMF5384Z/14/10/2024 11:27**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR FENDER INNER GARNISH RH <i>De band</i>	0.00	0.00	✓ *250.00 F
2	1		*REAR SPARE TYRE TOP BOX <i>De band</i>	0.00	0.00	✓ *120.00 F
3	1		*RACK END PANEL <i>Repeinted</i>	0.00	0.00	✗ *220.00 F
4	1		*REAR EXHAUST PIPE <i>Dented</i>	0.00	0.00	✓ *1,300.00 F
5	1		*REAR BOOT TRIM <i>Repeinted</i>	0.00	0.00	✗ *80.00 F
6	1		*REAR END PANEL TOP BOARD <i>De band</i>	0.00	0.00	✓ *110.00 F

F=Franchise part.

Sub Total (\$\$) 2,080.00**+ Margin on L,N Items 10.00% (\$\$)** 208.00**Total Parts (\$\$)** 2,288.00

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/14/10/2024 11:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Adrian G
Slip

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/14/10/2024 11:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >