

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	ICE SINGAPORE PL		Ref:	CS/SMO24100124/Anh3e2(N)	
	50 RAFFLES PLAC SINGAPORE LAN	CE #03-03 D TOWERSINGAPORE 048623		Date:	11/02/2025	
				Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SGB 6116S	Veh. Inspected		SKX 1772S	
	Policy No.	D24MTPV01004791	Coverage (\$)		0.00	
	Claim No.	CMTD2403226/GPL	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		07/10/2024	
2. Vehicle Particulars & Condition						
	Make & Model	NISSAN TEANA	c.c		1997	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	MNTBBAL33Z0005086	Colour		GREY	
	Odometer	99549 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/55 R17	DUNLOP		6 mm	
	L/H Front Tyre	215/55 R17	DUNLOP		6 mm	
	R/H Rear Tyre	215/55 R17	DUNLOP		6 mm	
	L/H Rear Tyre	215/55 R17	DUNLOP		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	03/10/2024	Inspection Dat	е	07/10/2024	
	Survey held at	AUTO UNITED SG PTE LTD				
		1 KAKI BUKIT AVENUE 6, #01-92, AUTOBAY@KAKI BUKIT, SINGAPORE 417883				
5a.		Remarks				
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days					
	•					