

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

45 9300

not Authorized
in
Mercedes

7/10/24

2/5 \$9300/
alphe-17th 1st
7 days

VEHICLE No: SGG 5505H

1PC	REAR WINDSCREEN	shortened	1288.60	\$1,650.00
1PC	REAR WINDSCREEN MOULDING	new	121.40	\$166.20
1PC	TAILGATE	30 day	1193.40	\$1,455.20
1PC	TAILGATE REAR LOGO	new		\$48.00
2PCS	TAILGATE REFLECTORS @\$441.60	new	380.60 x 2 = 761.20	\$883.20
1PC	TAILGATE 'SHUTTLE' EMBLEM	new	52.00	\$75.00
1PC	TAILGATE OUTER GARNISH	new	428.20	\$495.00
1PC	TAILGATE INNER LOCK	new	265.20	\$288.20
1PC	TAILGATE INNER TRIM BOARD	new	388.50	\$455.10
1PC	TAILGATE WEATHERSTRIP	new	185.40	\$232.80
1PC	REAR TAILGATE WIPER MOTOR	new		\$655.20
1PC	REAR WIPER ARM	11		\$211.80
2PCS	TAILLAMPS @\$950.00	new	455.30 x 2 = 910.60	\$1,900.00
1PC	REAR BUMPER	DIS	936.00	\$1,415.10
2PCS	REAR BUMPER SIDE RETAINERS @\$45.00	new		\$90.00
2PCS	REAR BUMPER REFLECTORS @\$75.00	new		\$150.00
2PCS	REAR BUMPER SIDE COVERS @\$111.00	new	88.50 x 2 = 177.00	\$222.00
1PC	REAR BUMPER INNER SPONGE	11		\$183.00
1PC	REAR BUMPER TOW COVER	new		\$45.00
1PC	REAR END PANEL	new	615.00	\$755.20
1PC	REAR END PANEL TOP GARNISH	new		\$248.70
1PC	REAR END PANEL ANTENNA SENSOR	11		\$108.90
2PCS	REAR END PANEL SIDE EXTENSION PANELS @\$285.00	new		\$570.00
1PC	REAR EXHAUST	11		\$688.20
1PC	REAR FLOOR PANEL TOP BOARD	new	482.50	\$544.10
1PC	REAR FLOOR PANEL	R		\$1,140.20
1PC	REAR FLOOR PANEL TOOLS TRAY	new	466.80	\$652.30
1PC	REAR BUMPER TOOLS SPONGE	11		\$588.00
2PCS	REAR FENDER INNER TRIM BOARDS @\$690.00	new	388 x 2 = 776.00	\$1,380.00
1PC	REAR FENDER	R		\$1,155.20
			202	\$18,451.60

S.NETT

1PC	REAR WINDSCREEN SOLAR FILM	new	\$250.00
1PC	REAR WINDSCREEN SEALANT	new	\$50.00
1PC	REAR WINDSCREEN INNER SEAL	new	\$50.00
1SET	REAR BUMPER REVERSE SENSOR	malfunction	\$280.00
1SET	REAR REVERSE CAMERA	malfunction/shorted	\$450.00
1SET	TAILGATE INNER TRIM BOARD CLIPS	11	\$50.00

1SET	REAR BUMPER CLIPS	111	\$60.00	30
1PC	REAR END PANEL SEALANT	11	\$50.00	X
1SET	REAR FLOOR PANEL INSULATOR	11	\$200.00	X
TO CHECK WIRING			\$50.00	20
TO DISMANTLE & REPLACED REVERSE SENSOR			\$80.00	30
TO DISMANTLE & REFIX REAR WINDSCREEN			\$150.00	120
TO DISMANTLE & REFIX CUSHION UPHOLSTERY			\$120.00	60
TO TRANSFER TAILGATE MECHANISM			\$100.00	60
TO SPRAY RUST PROOFING			\$100.00	60
TO RESET DIAGNOSTIC & REPROGRAMME SYSTEM			\$120.00	80
LABOUR FOR PANEL BEATING & REPLACED PARTS			\$1,800.00	800
TO PUTTY & SPRAY PAINTING			\$1,800.00	1000
TOTAL			\$24,211.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 1085470
202
8683.76
140
2230
11653.76
202
9323