

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax: 64747770

260, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax: 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax: 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 71401	Page No. : 1 of 5
Date Estimated : 04/10/2024	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Au Kah Wai, JEREMY (OU JIAWEI, JERE 334C Yishun Street 31 #03-111 Singapore 763334	- ACCOUNT - 115 United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore 068909
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMQ6315J	WBA6V120905P09878	27/11/2019	216i Gran Tourer	83815

DESCRIPTION	VALUE
Replace front support panel, front bumper include attachment etc and carryout necessary repairing work on accident damage area	2550 / 1700 3,400.00
Painting front bumper and bonnet	2336 2,336.00
To check electrical wiring system at the front section for proper function.	177.00
To replace left headlight.	481.00
Sundries. nec	150.00
Total Labour 1:	6,544.00

DESCRIPTION	QTY	PRIC	VALUE
FRT BUMPER LH INSERT ? x su	1	15.85	15.85
FRT BUMPER RH INSERT ? x su	1	15.85	15.85
FRT LH SIDE PANEL TOP MOUNTING ? x su	1	57.55	57.55
FRT RH SIDE PANEL TOP MOUNTING ? x su	1	57.55	57.55
LH FOG LAMP SUPPORT ? cm	1	165.15	165.15
LH MOUNTING PMA SENSOR ? x su	1	23.65	23.65
FRT BUMPER TOP CARRIER ? bt	1	420.15	420.15
LH FINISHER cm	1	55.45	55.45
LH MOLDING (SPORT) cm	1	62.55	62.55
IMPACT ABSORBER TOP ? cm	1	64.00	64.00
TRIM STRIP CENTRE (SPORT) cut	1	55.05	55.05
COVERING CENTER ? x su	1	76.40	76.40
FRT BUMPER PANEL PRIMED (BASIS) de	1	987.80	987.80
LH GRID LATERAL (LINES/PDC) ? cm	1	102.35	102.35
FRT LH GRILLE cm	1	125.55	125.55
GROMMET x cm	2	0.80	1.60
LH BOTTOM ADAPTER ? x su	1	112.30	112.30
LH AIR DUCT DISPLACED RADIATOR ? cm	1	81.35	81.35
AIR DUCT ? cm	1	562.10	562.10
PLAQUE 82MM	1	76.55	76.55

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 71401
Date Estimated : 04/10/2024
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMQ6315J	WBA6V120905P09878	27/11/2019	216i Gran Tourer	83815

DESCRIPTION	QTY	PRIC	VALUE
LH HEADLIGHT LED TECHNOLOGY <i>br /</i>	1	2,503.55	2,503.55
ULTRASONIC SENSOR BLACK <i>ysu</i>	1	269.65	269.65
DECOUPING RING PDC TORQUE CONVERTER <i>u Xnn</i>	6	5.65	33.90
ULTRASONIC SENSOR side <i>ysu</i>	1	391.40	391.40
Total Parts :			6,317.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims ODY 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 09/10/24 Excess S\$ TBA
Surveyor's Name Ratul Sign _____
Surveyor's Tel 90014068 Authorised Yes ☒ No ☐
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
Surveyor's E-mail _____
No. of Working Days Recommend 5 days

Reg 68 part



Labour 1	:	6,544.00
Parts	:	6,317.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	1,157.52
Grand Total	:	14,018.82

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **