

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 09 Oct 2024

Preliminary Advice

Insured Vehicle No	: SJH8880M	Accident Date	: 03/10/2024
TP Vehicle No	: SDU9222J	Assignment Date	: 08/10/2024
Make	: BMW X3	Est. Duration of Repair	: 0
Date of Inspection	: 07/10/2024		
Inspection At	: YSK AUTO WORKSHOP (HQ) 1 KAKI BUKIT AVENUE 6 @ AUTOBAY, #01-71 SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	Total loss
Revised Amount	:S\$	Total loss
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	38,000.00
COE / PARF Rebate	:S\$	27,294.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,706.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (x) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :