

ABWIN SERVICE PTE LTD

176 SIN MING DRIVE
#01-11 SIN MING AUTOCARE, SINGAPORE 575721
Tel: 65179701 Fax: 65179704
Email: servicecentre@abwinm9.com Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

ABWIN
Service Pte Ltd**M9 Automobile Pte Ltd**
M9 International Pte Ltd

Not Notified
1 Day @ 6250/-
Running After Paim

ESTIMATED COST: HQQ001031

TO : ECICS LIMITED
ATTN : MOTOR CLAIM DEPARTMENT

GBE5995Y
STARITZ GLOBAL PTE. LTD.
CONTACT NO : 90079791

Today

DATE : 28-NOV-2024
MAKE : NISSAN
MODEL : CABSTAR 3.0 5M/T ABS 2DR
2WD EURO 5
CHASSIS NO : JN1SC2F24Z0858065
ENGINE NO : ZD30007664N
SERVICE ADVISOR : MIKAELA
PAGE : 1 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
LIST ITEM			
1	FRONT GRILLE <i>578.60</i>	<i>CM</i> 725.00 <i>—</i>	
1	FRONT GRILLE EMBLEM	<i>me</i> 79.00 <i>—</i>	
1	'CABSTAR' LOGO	<i>me</i> 55.00 <i>X</i>	
1	BUMPER FRONT <i>945</i>	<i>Ry</i> 1,303.00 <i>✓</i>	
1	HEADLAMP LH	<i>CRP</i> 615.00 <i>✓</i>	
1	CORNER PANEL LH	<i>Sm</i> 472.50 <i>X</i>	
1	SIDE MIRROR LH	<i>Sm</i> 222.00 <i>X</i>	
1	SIDE MIRROR HOLDER LH	<i>R</i> 269.00 <i>X</i>	
1	SPARE TYRE PANEL	<i>R</i> 1,800.00 <i>X</i>	
Sub Total		5,540.50	0.00

SPECIAL NETT

1	NUMBER PLATE FRONT	<i>Ry</i> 50.00 <i>25.00</i>	
1	NUMBER PLATE REAR	<i>Ry</i> 50.00 <i>25.00</i>	
1	REAR CABIN DOOR LH	<i>Ry</i> 1,550.00 <i>—</i>	
1	REAR CABIN DOOR RH	<i>Ry</i> 1,550.00 <i>—</i>	
1	REAR CABIN DOOR HINGE RH	<i>R</i> 280.00 <i>X</i>	
1	REAR CABIN DOOR HINGE LH	<i>mi</i> 280.00 <i>✓</i>	
1	70KM STICKER	<i>me</i> 45.00 <i>15.00</i>	
1	REAR CABIN LOCK RH	<i>Ry</i> 580.00 <i>✓</i>	
Sub Total		4,385.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1,800.00 <i>1000/-</i>	
1	TO SPRAY PAINT ON AFFECTED AREAS	1,800.00 <i>400/-</i>	
1	TO APPLY UNDERCOATING FOR RUST PROOFING	<i>me</i> 200.00 <i>X</i>	
Sub Total		3,800.00	0.00

Auto Consultants hence notify the Resurveyor the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ABWIN SERVICE PTE LTD

176 SIN MING DRIVE

#01-11 SIN MING AUTOCARE, SINGAPORE 575721

Tel: 65179701 Fax: 65179704

Email: servicecentre@abwinm9.com Website: www.abwinm9.com

Company Reg. No: 201318685G GST Reg. No: 201318685G

ABWIN
Service Pte Ltd**M9 Automobile Pte Ltd**
M9 International Pte Ltd**SUPPLEMENTARY: HQQ001035****TO : ECICS LIMITED**
ATTN : MOTOR CLAIM DEPARTMENT**GBE5995Y**
STARITZ GLOBAL PTE. LTD.
CONTACT NO : 90079791

DATE	:	03-DEC-2024
MAKE	:	NISSAN
MODEL	:	CABSTAR 3.0 5M/T ABS 2DR
	:	2WD EURO 5
CHASSIS NO	:	JN1SC2F24Z0858065
ENGINE NO	:	ZD30007664N
SERVICE ADVISOR	:	JINGNI
PAGE	:	1 OF 1

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
LIST ITEM			
1	SIGNAL LAMP LH <i>B2</i>	219.90	✓
1	SIGNAL LAMP LH COVER <i>B2</i>	89.60	✓
1	HEADLAMP BRACKET LH	<i>m/cm</i> 59.60	✓
1	END PANEL <i>597.30</i>	<i>B2</i> 1,233.90	✓
1	VERTICAL PANEL	<i>X</i> 1,022.90	X
1	VERTICAL SUPPORT PANEL	<i>n</i> 1,378.60	X
	Sub Total	4,004.50	0.00

SPECIAL NETT

1	REAR CABIN SPONGE LH	<i>nn</i> 120.00	X
	Sub Total	120.00	0.00

LABOUR

1	TO REALIGN FRONT CABIN	350.00 <i>2001</i>	
	Sub Total	350.00	0.00

SUB-TOTAL	4,474.50	0.00
GST - 9 %	402.71	0.00
TOTAL	4,877.21	0.00

ABWIN SERVICE PTE LTD

Prepared By