

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 24 Dec 2024

Preliminary Advice

Insured Vehicle No	: GBH2224S	Accident Date	: 04/10/2024
TP Vehicle No	: GBE5995X	Assignment Date	: 08/10/2024
Make	: NISSAN CABSTAR	Est. Duration of Repair	: 8
Date of Inspection	: 02/12/2024		
Inspection At	: ABWIN SERVICE PTE LTD (575721) 176 SIN MING DRIVE, #01-11 AUTOCARE SINGAPORE		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,200.00
Revised Amount	:S\$	8,490.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,490.60
Lump Sum Repair	:S\$	6,250.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.