

ASS. REC. BY:

REF:

C/10524100129/Kqk3

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/ MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / 29 not ready

9/12 11/12 @ 6250/1 Cabnet (Veh # 11950, 66%)

Date/Time, File Pass to?

1) 24/12 11/12

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.A. (\$) 6750

MER-TP

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

**ABWIN SERVICE PTE LTD**

176 SIN MING DRIVE  
 #01-11 SIN MING AUTOCARE, SINGAPORE 575721  
 Tel: 65179701 Fax: 65179704  
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com  
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ABWIN**  
 Service Pte Ltd

M9 Automobile Pte Ltd  
 M9 International Pte Ltd

*Not withstanding  
 C1 Reg & 6250/h  
 Running After Pain*

**ESTIMATED COST: HQQ001031**

**TO : ECICS LIMITED**  
**ATTN : MOTOR CLAIM DEPARTMENT**

**GBE5995Y**  
**STARITZ GLOBAL PTE. LTD.**  
 CONTACT NO : 90079791

*7 days*

DATE : 28-NOV-2024  
 MAKE : NISSAN  
 MODEL : CABSTAR 3.0 5M/T ABS 2DR  
 2WD EURO 5  
 CHASSIS NO : JN1SC2F24Z0858065  
 ENGINE NO : ZD30007664N  
 SERVICE ADVISOR : MIKAELA  
 PAGE : 1 OF 2

| QTY              | DESCRIPTION                | REPAIR AMOUNT (SGD)  | SURVEYOR APP (SGD) |
|------------------|----------------------------|----------------------|--------------------|
| <b>LIST ITEM</b> |                            |                      |                    |
| 1                | FRONT GRILLE <i>578.60</i> | <i>CM</i> 725.00 —   |                    |
| 1                | FRONT GRILLE EMBLEM        | <i>me</i> 79.00 —    |                    |
| 1                | 'CABSTAR' LOGO             | <i>me</i> 55.00 X    |                    |
| 1                | BUMPER FRONT <i>945</i>    | <i>Ry</i> 1,303.00 ✓ |                    |
| 1                | HEADLAMP LH                | <i>CM</i> 615.00 ✓   |                    |
| 1                | CORNER PANEL LH            | <i>Sm</i> 472.50 X   |                    |
| 1                | SIDE MIRROR LH             | <i>Sm</i> 222.00 X   |                    |
| 1                | SIDE MIRROR HOLDER LH      | <i>R</i> 269.00 X    |                    |
| 1                | SPARE TYRE PANEL           | <i>R</i> 1,800.00 X  |                    |
| <b>Sub Total</b> |                            | <b>5,540.50</b>      | <b>0.00</b>        |

**SPECIAL NETT**

|                  |                          |                             |             |
|------------------|--------------------------|-----------------------------|-------------|
| 1                | NUMBER PLATE FRONT       | <i>Ry</i> 50.00 <i>25In</i> |             |
| 1                | NUMBER PLATE REAR        | <i>Ry</i> 50.00 <i>25In</i> |             |
| 1                | REAR CABIN DOOR LH       | <i>Ry</i> 1,550.00 —        |             |
| 1                | REAR CABIN DOOR RH       | <i>Ry</i> 1,550.00 —        |             |
| 1                | REAR CABIN DOOR HINGE RH | <i>R</i> 280.00 X           |             |
| 1                | REAR CABIN DOOR HINGE LH | <i>mi</i> 280.00 —          |             |
| 1                | 70KM STICKER             | <i>me</i> 45.00 <i>15In</i> |             |
| 1                | REAR CABIN LOCK RH       | <i>Ry</i> 580.00 ✓          |             |
| <b>Sub Total</b> |                          | <b>4,385.00</b>             | <b>0.00</b> |

**LABOUR**

|                  |                                                                |                       |             |
|------------------|----------------------------------------------------------------|-----------------------|-------------|
| 1                | TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS | 1,800.00 <i>1000l</i> |             |
| 1                | TO SPRAY PAINT ON AFFECTED AREAS                               | 1,800.00 <i>400l</i>  |             |
| 1                | TO APPLY UNDERCOATING FOR RUST PROOFING                        | <i>me</i> 200.00 X    |             |
| <b>Sub Total</b> |                                                                | <b>3,800.00</b>       | <b>0.00</b> |

Link Auto Consultants hence notify the Resurveyor the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**ABWIN SERVICE PTE LTD**

176 SIN MING DRIVE  
#01-11 SIN MING AUTOCARE, SINGAPORE 575721  
Tel: 65179701 Fax: 65179704  
Email: servicecentre@abwinm9.com Website: www.abwinm9.com  
Company Reg. No: 201318685G GST Reg. No: 201318685G

**ABWIN**  
Service Pte Ltd**M9 Automobile Pte Ltd**  
**M9 International Pte Ltd****ESTIMATED COST: HQQ001031**

**TO : ECICS LIMITED**  
**ATTN : MOTOR CLAIM DEPARTMENT**

**GBE5995Y**  
**STARITZ GLOBAL PTE. LTD.**  
CONTACT NO : 90079791

DATE : 28-NOV-2024  
MAKE : NISSAN  
MODEL : CABSTAR 3.0 5M/T ABS 2DR  
2WD EURO 5  
CHASSIS NO : JN1SC2F24Z0858065  
ENGINE NO : ZD30007664N  
SERVICE ADVISOR : MIKAELA  
PAGE : 2 OF 2

| QTY | DESCRIPTION | REPAIR AMOUNT (SGD) | SURVEYOR APP (SGD) |
|-----|-------------|---------------------|--------------------|
|-----|-------------|---------------------|--------------------|

|                  |                  |             |
|------------------|------------------|-------------|
| <b>SUB-TOTAL</b> | <b>13,725.50</b> | <b>0.00</b> |
| <b>GST - 9 %</b> | <b>1,235.30</b>  | <b>0.00</b> |
| <b>TOTAL</b>     | <b>14,960.80</b> | <b>0.00</b> |

**ABWIN SERVICE PTE LTD**

Prepared By

1985.24  
889.76  
1400  
3445  
710.60  
↑  
615

615  
710  
5mm  
1600.00  
4025.00  
2865.60  
3184.00

**ABWIN SERVICE PTE LTD**

176 SIN MING DRIVE  
 #01-11 SIN MING AUTOCARE, SINGAPORE 575721  
 Tel: 65179701 Fax: 65179704  
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com  
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ABWIN**  
 Service Pte Ltd



**M9 Automobile Pte Ltd**  
**M9 International Pte Ltd**

**SUPPLEMENTARY: HQQ001035**

**TO : ECICS LIMITED**  
**ATTN : MOTOR CLAIM DEPARTMENT**

**GBE5995Y**  
**STARITZ GLOBAL PTE. LTD.**  
 CONTACT NO : 90079791

DATE : 03-DEC-2024  
 MAKE : NISSAN  
 MODEL : CABSTAR 3.0 5M/T ABS 2DR  
 2WD EURO 5  
 CHASSIS NO : JN1SC2F24Z0858065  
 ENGINE NO : ZD30007664N  
 SERVICE ADVISOR : JINGNI  
 PAGE : 1 OF 1

| QTY                 | DESCRIPTION                       | REPAIR AMOUNT (SGD) | SURVEYOR APP (SGD) |
|---------------------|-----------------------------------|---------------------|--------------------|
| <b>LIST ITEM</b>    |                                   |                     |                    |
| 1                   | SIGNAL LAMP LH <i>Bo</i>          | 219.90              | —                  |
| 1                   | SIGNAL LAMP LH COVER <i>Bo</i>    | 89.60               | ✓                  |
| 1                   | HEADLAMP BRACKET LH               | <i>m/cm</i> 59.60   | ✓                  |
| 1                   | END PANEL <i>597.30</i>           | <i>R</i> 1,233.90   | ✓                  |
| 1                   | VERTICAL PANEL                    | <i>R</i> 1,022.90   | X                  |
| 1                   | VERTICAL SUPPORT PANEL <i>108</i> | <i>R</i> 1,378.60   | X                  |
|                     | <b>Sub Total</b>                  | <b>4,004.50</b>     | <b>0.00</b>        |
| <b>SPECIAL NETT</b> |                                   |                     |                    |
| 1                   | REAR CABIN SPONGE LH              | <i>nn</i> 120.00    | X                  |
|                     | <b>Sub Total</b>                  | <b>120.00</b>       | <b>0.00</b>        |
| <b>LABOUR</b>       |                                   |                     |                    |
| 1                   | TO REALIGN FRONT CABIN            | 350.00 <i>200L</i>  |                    |
|                     | <b>Sub Total</b>                  | <b>350.00</b>       | <b>0.00</b>        |

|                  |                 |             |
|------------------|-----------------|-------------|
| <b>SUB-TOTAL</b> | <b>4,474.50</b> | <b>0.00</b> |
| <b>GST - 9 %</b> | <b>402.71</b>   | <b>0.00</b> |
| <b>TOTAL</b>     | <b>4,877.21</b> | <b>0.00</b> |

**ABWIN SERVICE PTE LTD**

Prepared By