



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNS 8837J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT GRILLE	CUT	\$1,150.00	\$1,150.00
1	FRONT BUMPER	DEFORMED	\$2,875.00	\$2,875.00
2	FRONT BUMPER SIDE HOLDER @\$39.10	NOT NECESSARY	\$78.20	\$0.00
1	FRONT BUMPER CENTRE GARNISH	CUT	\$460.00	\$460.00
1	FRONT BUMPER RH SIDE GARNISH	CRACKED	\$184.00	\$184.00
1	FRONT BUMPER RH SIDE LOWER MOULDING	CUT	\$379.50	\$379.50
1	FRONT BUMPER CENTRE LOWER MOULDING	NOT NECESSARY	\$425.50	\$0.00
1	FRONT BUMPER LOWER CENTRE COVER	DEFORMED	\$805.00	\$805.00
4	FRONT BUMPER SENSOR @\$417.80	DAMAGED (1PC ONLY)	\$1,035.00	\$250.00
1	FRONT NUMBER PLATE	CUT	\$100.00	\$50.00
1	FRONT NUMBER PLATE HOLDER	CUT	\$50.00	\$30.00
1	FRONT NUMBER PLATE GARNISH	CRACKED	\$184.00	\$184.00
1	FRONT GRILLE LAND ROVER EMBLEM	NECESSARY	\$253.00	\$253.00
1	FRONT BUMPER INNER SPONGE	NOT NECESSARY	\$218.50	\$0.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	\$977.50	\$0.00
1	FRONT BUMPER RH SIDE LAMP	CRACKED	\$816.50	\$515.00
	LESS 5.00 / 10.00% DISCOUNT		(\$499.59)	(\$713.55)
			\$9,492.11	\$6,421.95

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE, REPLACE + REPAIR CONSISTENT TO THE ACCIDENT		\$1,000.00	\$350.00
	RESPRAY PAINTING		\$800.00	\$250.00
	RESET	NOT NECESSARY	\$100.00	\$0.00
			\$1,900.00	\$600.00

GRAND TOTAL	\$11,392.11	\$7,021.95
--------------------	--------------------	-------------------

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	\$5,600.00
---	-------------------

Report Ref No: CS/INC24100131/Aqh3e2

TOTAL FOR SPARE PARTS: \$ 9,492.12 \$ 6,421.95
TOTAL FOR LABOUR : \$ 1,900.00 \$ 600.00
TOTAL REPAIR COST: \$ 11,392.12 \$ 7,021.95



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.