

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #01-77 AUTOBAY@KAKI BUKIT
SINGAPORE 417883
TEL: 92327457

TO	: NTUC	DATE	: 14/10/2024
VEHICLE NO	: SLZ9338M (2018)		
VEHICLE MODEL	: INFINITI Q50		
CHASSIS NO	: JN1BCAV37Z0530150		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Dehco</i>	1	\$ 884.50	\$ 884.50
2	REAR BUMPER SIDE HOLDER <i>Ken</i>	2	\$ 66.50	\$ 133.00
3	REAR BUMPER TOW COVER <i>Ken</i>	1	\$ 35.10	\$ 35.10
4	REAR BUMPER REINFORCEMENT <i>Dehco</i>	1	\$ 681.90	\$ 681.90
5	REAR BUMPER REINFORCEMENT STAY <i>Ken</i>	2	\$ 185.00	\$ 370.00
6	REAR BUMPER REINFORCEMENT BRACKET <i>Ken</i>	3	\$ 58.20	\$ 174.60
7	REVERSE SENSOR <i>1 piece damaged</i>	4	\$ 224.00	\$ 896.00

TOTAL PRICE: \$ 3,175.10
LESS 10% \$ 317.51
SUB TOTAL PRICE: \$ 2,857.59

1790.40

1611.36

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>Ken</i>	1 SET	\$ 50.00	\$ 50.00

TOTAL : \$ 50.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 400.00	<i>300</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 400.00	<i>200</i>	
3	WIRING CHECK	\$ 50.00	<i>50</i>	
4	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	

TOTAL: \$ 950.00

\$50

ESTIMATE REPORT

TOTAL PARTS COST: \$ 2,907.59
TOTAL LABOUR COST: \$ 950.00
TOTAL REPAIR COST: \$ 3,857.59

total: 2811.36

L/S: 1750

02 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: