

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3157/10/24

Your Ref:

Date: 4th October 2024

MR KOH PUAY SENG
BLK 56, Choa Chu Kang North 6,
#18-35, Singapore 689577

4 days.
Whepho Atten -

Estimate cost of repair to HONDA ACCORD 2.0 (A) saloon - SND 1255 M

1 pc o/s head lamp assy	Cia	2880.90	\$ 2,949.90
1 pc o/s head lamp lower bracket	CNE		46.20
1 pc front bumper	Cut/Toon	620.50	650.50
1 pc front bumper o/s side retainer	CNE		38.40
10 pcs front bumper clips	Her	4.90	49.00
1 pc front bumper o/s side bracket clip	17		5.90
1 pc front o/s fender	Buc		597.60
1 pc front o/s fender inner shield guard	Her		239.30
8 pcs front o/s fender inner shield clips	Her	3.90	31.20
1 pc front bumper o/s fog lamp garnish	17		165.10
1 pc front grille	17		564.50
1 pc front grille top chrome moulding	CNE		470.30
8 pcs front grille clips	17	4.90	39.20
1 pc washer tank	De		90.80
1 pc front support panel	N		792.00

Less 20% \$ 1,345.98

\$ 5,383.92

To wiring check up & adjust headlight alignment. 50.00 20

To check & adjust front wheel alignment & balancing. 150.00 60

To respray Tuff-Kote on all affected accident parts. 90.00 30

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front support panel, front bonnet, front support panel & necessary parts, to weld, renew & align above parts. 1,250.00 680

To putty & respray painting on all affected accident parts. 1,450.00 800

\$ 8,373.90

=====

Dollars : Eight Thousand Three Hundred Seventy Three And Cents Ninety Only.

HUP MOTOR TRADING & SERVICE

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 50642

20%

4051.36

1590

5641.36

202

4513