

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2410-642

DATE : 1-Oct-2024

POLICY NO. : BD P10815438R01

VEHICLE REG. NO. : SJU7039P

VEHICLE MAKE : KIA CERATO FORTE 1.6SX AT

TO SPC Accident Claims Section
Logistics Support & Services Division
Police Logistics Department, Police Logistics Base
1 Hemmant Road, Singapore 438675
Tel: 68428401, Fax: 64784848

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper / BR	1	\$ 700.00	\$ 700.00
2	Front Bumper Clip / MC	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer RH X	1	\$ 50.00	\$ 50.00
4	Front Bumper Retainer LH X	1	\$ 50.00	\$ 50.00
5	Front Reinforcement X	1	\$ 480.00	\$ 480.00
6	Front Sponge/absorber X	1	\$ 200.00	\$ 200.00
7	Front License Garnish X	1	\$ 60.00	\$ 60.00
8	Front Grille Assy / BR	1	\$ 580.00	\$ 580.00
9	Front Headlamp RH X	1	\$ 600.00	\$ 600.00
10	Front Headlamp LH / cut	1	\$ 600.00	\$ 600.00
11	Front Support Panel X	1	\$ 500.00	\$ 500.00
12	Front Bonnet / M	1	\$ 800.00	\$ 800.00
13	Front Bonnet Insulator Clip / MC	10	\$ 5.00	\$ 50.00
14	Front Bonnet Lock X	1	\$ 80.00	\$ 80.00
15	Front Bonnet / Top Cover Rubber Seal / CPY	1	\$ 50.00	\$ 50.00
16	Front Bonnet Hinge RH X	1	\$ 50.00	\$ 50.00
17	Front Bonnet Hinge LH X	1	\$ 50.00	\$ 50.00
18	AC Condenser X	1	\$ 800.00	\$ 800.00
19	Radiator X	1	\$ 650.00	\$ 650.00
Total Spare Parts				\$ 6,400.00
SPECIAL NETT				
20	Front Number Plate with Frame X NY	1	\$ 40.00	\$ 40.00
21	Coolant Fluid 4 Litres X	1	\$ 35.00	\$ 35.00
Total Special Nett				\$ 75.00
LABOUR				
22	Spray Painting Front Bumper, Front Bonnet, Front Support Panel Including Blending	1	\$ 700.00	\$ 700.00
23	Remove and Refit Front & Rear Affected Area	1	\$ 700.00	\$ 700.00
24	Remove and Refit A/C Condenser, Radiator Including A/C Gas	1	\$ 100.00	\$ 100.00
25	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
26	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2410-642

DATE : 1-Oct-2024

POLICY NO. : BD P10815438R01

VEHICLE REG. NO. : SJU7039P

VEHICLE MAKE : KIA CERATO FORTE 1.6SX AT

TO SPC Accident Claims Section
Logistics Support & Services Division
Police Logistics Department, Police Logistics Base
1 Hemmant Road, Singapore 438675
Tel: 68428401, Fax: 64784848

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Estimate prepared by: Oscar Pong				
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.				
Total Labour				\$ 1,630.00
Amount Before Excess				\$ 8,105.00
Add GST @ 9%				729.45
Total Amount Payable				\$ 8,834.45

Stew (LKK)

21/10/24, 10.10 am

m ll

L/S

W AL 14
4 d p

Stew (LKK) auto - con

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: