



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

1 July 2024

REG NO.: SJL 1293 H
MAKE/MODEL: TOYOTA COROLLA ALTIS

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front headlamp -RH	\$ 1 1 930.50 X
1	Front grille	\$ 1 1 312.80 X
1	Front grille logo	\$ 1 1 68.55 X
1	Front grille chrome moulding - lower	\$ 1 1 68.75 X
1	Front grille chrome moulding - top	\$ 1 1 48.26 X
1	Front bumper	\$ 1 1 552.90 X
1	Front bumper centre grille	\$ 1 1 101.80 X
1	Front bumper fog lamp	\$ 1 1 280.70 X
1	Front bumper fog lamp cover	\$ 1 1 56.07 X
1	Front bumper reinforcement	\$ 1 1 399.66 X
2	Front bumper side retainers	\$ 1 1 99.68 X
1	Front fender -RH	\$ 1 1 525.00 X
		\$ 3,444.67
Less 25%		\$ 861.17
		\$ 2,583.50

<u>SPECIAL NETT ITEMS</u>		
1	Front bumper clip (1 set)	\$ 1 1 35.00 X
		\$ 35.00

S/N	LABOUR CHARGES	
1	To check wiring and reset headlamps focusing.	\$ 80.00 20
2	To apply undercoating.	\$ 1 1 100.00 X
3	Panel beating.	\$ 1,400.00 200
4	To re-spray painting on the affected areas.	\$ 1,200.00 400
		\$ 2,780.00

\$ 5,398.50

LKK Auto Consultants hence notify
the Repairer of the following.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: