

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24100139/TVH3E2
Date: 14/10/2024REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAB00167
Claimant Vehicle No :	SHA4588U	Insured Vehicle No :	SLJ3268E
Date of Loss:	04/10/2024	Nature of Claim:	TP
		Claim No:	M2405817

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA4588U		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2C18417
Reg. Date:	15/05/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU403080674
Colour:	Blue	Odometer:	0 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,348.47	1,536.50	811.97	34.57
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	860.00	720.00	140.00	16.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,220.47	2,268.50	951.97	29.56
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	3,220.47	1,800.00	1,420.47	44.11
+ GST 9.00/9.00% (S\$)	289.84	162.00	127.84	44.11
Nett Amount (S\$)	3,510.31	1,962.00	1,548.31	44.11

INSPECTION

Date of Assignment:	07/10/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	07/10/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2024)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA4588U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	503.04 FL	*503.04 FL
2	1		*REAR BUMPER CTR MOULDING	Cut	654.96 FL	*654.96 FL
3	1		*REAR BUMPER TOW COVER	Not Necessary	82.70 FL	*- FL
4	1		*REAR BUMPER EXTENSION LH	Deformed	232.00 FL	*232.00 FL
5	1		*REAR BUMPER RETAINER LH	Not Necessary	112.70 FL	*- FL
6	1		*TAILLAMP UPPER LH	Not Necessary	557.90 FL	*- FL
7	1		*TAILLAMP LOWER LH	Cracked	570.00 FL	*570.00 FL
8	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
9	1		*REAR BUMPER SIDE UNDER COVER LH	Not Necessary	148.40 FL	*- FL
10	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F
11	1		*REVERSE SENSORS	Not Necessary	135.70 F	*- F
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	3,069.40 2,032.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	720.93 495.50
					Total Parts (\$\$)	2,348.47 1,536.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (S\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	380.00
2	SPRAY PAINTING	New	300.00	280.00
3	R/I REVERSE SENSORS	New	120.00	30.00
4	CHECK LIGHTINGS	New	40.00	30.00
Gross Labour Cost (S\$)			860.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >