



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO XE 2917G

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER BOTTOM LH	REPAIRED SEE LABOUR	\$1,280.00	\$0.00
1	FRONT BUMPER SIDE GARNISH LH (CUT)	NOT CONSISTENT WITH THE IMPACT	\$340.62	\$0.00
1	FRONT DOOR OUTER HANDLE LH (CUT)	NOT CONSISTENT WITH THE IMPACT	\$620.30	\$0.00
1	SIDE PANEL LH	REPAIRED SEE LABOUR	\$1,557.20	\$0.00
1	SIDE PANEL '370' LH	REPLACED	\$128.00	\$128.00
1	SIDE PANEL 'EURO 5' LH	REPLACED	\$95.00	\$95.00
1	REAR PILLAR LH	REPAIRED SEE LABOUR	\$568.00	\$0.00
1	SIDE GUARD LH	REPAIRED SEE LABOUR	\$988.00	\$0.00
1	REAR FENDER LH	REPAIRED SEE LABOUR	\$645.00	\$0.00
	<b>LESS 10.00% DISCOUNT</b>		(\$622.21)	(\$22.30)
			<b>\$5,599.91</b>	<b>\$200.70</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR LH (SN) (LOCAL REPAIR)	REPLACED	\$3,459.60	\$300.00
1	FRONT DOOR STICKER LH (SN)	REPLACED	\$120.00	\$60.00
			<b>\$3,579.60</b>	<b>\$360.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT BUMPER BOTTOM LH, SIDE PANEL LH, REAR PILLAR LH, SIDE GUARD LH AND REAR FENDER LH	NOT NECESSARY	\$3,800.00	\$600.00
	RE-SEAL ANTI RUST		\$200.00	\$0.00
	TO CHECK WIRING		\$120.00	\$20.00
	TO PUTTY AND RE-SPRAY PAINTING		\$2,200.00	\$800.00
			\$6,320.00	\$1,420.00

<b>GRAND TOTAL</b>	<b>\$15,499.51</b>	<b>\$1,980.70</b>
--------------------	--------------------	-------------------

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>		<b>\$1,550.00</b>
---	--	-------------------

Report Ref No: CS/LIP24100140/Kqh3e2

MARKET VALUE: \$42,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$5,855.00=NETT VALUE: \$36,145.00



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

**KSC**

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.