

5b.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
S LIBERTY INSURANCE PTE LTD		Ref:	CS/LIP24100140/Kqh3e2
ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583		Date:	25/10/2024
		Code:	LIP
1. Policy Particulars :- THIRD PARTY CLAIM (PHYSICAL REINSPECTION)			
Insured Veh.	YM 8155U	Veh. Inspected	XE 2917G
Policy No.	SI23V04338/VCH/R04	Coverage	0
Claim No.	IVS24/1008	Excess	\$0.00
Assign From	STEWART LIM	Assign Date	04/10/2024
2. Vehicle Details			
Make & Model	VOLVO FMX370 (A)	C.C	10837
Engine No.	D11400325	Year of Reg.	04/05/2017
Chassis No.	YV2X1E1D3HB805510	Colour	BLUE
Odometer	365401 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		
3. Conditions of Tyres			
	Size	Make	Balance (mm)
R/H Front Tyre	315/80 R22.5	SAILMAX	8
L/H Front Tyre	315/80 R22.5	SAILMAX	8
R/H Rear Tyre	315/80 R22.5 (D/D)	GOODYEAR	2/2/6/6
L/H Rear Tyre	315/80 R22.5 (D/D)	GOODYEAR	2/2/6/6
4. Description of Damages			
VEHICLE HAD CO	MPLETED ITS REPAIR WORKS.		
AIR CONDITION SE	E DETAILS.		
5. General Information			
Accident Date	24/05/2024	Inspection Date	16/10/2024
Survey held at	BLOCK 32, SIN MING DRIVE, #01-349 S 575706 - REPAIRER: HC AUTO & MOTORS SERVICE		
	Rema	arks	
	Insured Veh. Policy No. Claim No. Assign From Make & Model Engine No. Chassis No. Odometer Brakes Modification(s) R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre L/H Rear Tyre ACCIDENTION SE	Policy Particulars:-THIRD PARTY (Insured Veh. YM 8155U Policy No. SI23V04338/VCH/R04 Claim No. IVS24/1008 Assign From STEWART LIM Vehicle Make & Model VOLVO FMX370 (A) Engine No. D11400325 Chassis No. YV2X1E1D3HB805510 Odometer 365401 KM Brakes IN ORDER Modification(s) RIMS: NIL Conditions Size R/H Front Tyre 315/80 R22.5 (D/D) L/H Rear Tyre 315/80 R22.5 (D/D) L/H Rear Tyre 315/80 R22.5 (D/D) CVEHICLE HAD COMPLETED ITS REPAIR WORKS. AIR CONDITION SEE DETAILS. General In Accident Date 24/05/2024 Survey held at BLOCK 32, SIN MING DRIVE, #01-34 SERVICE	Note

Estimate Days of Repair

A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.