

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24100143/UUA3Q2

Date: 02/12/2024

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D24MPC0004178
Claimant Vehicle No :	FBL2396H	Insured Vehicle No :	SLQ1405C
Date of Loss:	22/09/2024	Nature of Claim:	TP
			Claim No: MPC2024D0011110

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL2396H	Engine No:	E3F5E041993
Make & Model:	YAMAHA YBR125, 124cc (M)	Chassis No:	LBPRE101000056956
Reg. Date:	28/07/2016 (Man. Year: 2016)	Odometer:	97164 km
Colour:	White		
Engine Capacity:	124 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	2.75-18	Rear Tyre Size:	90-90-18
Front Left Side:	Timsun 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	729.00	174.60	554.40	76.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	232.00	80.00	152.00	65.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	961.00	254.60	706.40	73.51
Approved Total (Overridden) (\$\$)		200.00		
Nett Amount (\$\$)	961.00	200.00	761.00	79.19
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	08/10/2024	Ban Hock Hin Co. Pte Ltd (HQ)
Date Inspected:	08/10/2024 Inspected At:	BLK 8 Defu South Street 1, #04-28 JTC Defu Industrial City
Estimated Period of Repair:	1.0 days	Singapore 533758

Adjuster: MARCUS CHUA

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 02 Dec 2024)	
Parts:	N/A	YAMAHA YBR125 124cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL2396H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CRASH BAR	Not Necessary	225.00 F	*- FL
2	1		*FOOT REST FRONT & BODY ALIGNMENT	Not Necessary	310.00 F	*- FL
3	1		*PROTECTOR EXHAUST	Cut	132.00 F	*132.00 FL
4	1		*PROTECTOR EXHAUST CAP	Cut	62.00 F	*62.00 FL
					Sub Total (\$\$)	729.00 194.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 19.40
					Total Parts (\$\$)	729.00 174.60

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR QUOTED FOR DISMANTLING & INSTALLATION OF PARTS	New	170.00	80.00
2	TRANSPORT CHARGES	New	62.00	0.00
Gross Labour Cost (S\$)			232.00	80.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >