



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

INDIA INTERNATIONAL INSURANCE P.L.

64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711

ATTN: MOTOR CLAIMS DEPT

NO. : 47899

DATE : 07/10/2024
CLAIM NO. : 12620
POLICY NO. : MC/01645427

FROM : RAYMOND

VEHICLE NO. : FBL2396H
MAKE/MODEL : YAM / YBR125

not authorized
8/10/24
1/5 \$200
1 day
Chap. Attorney

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	CRASH BAR P/N: 35878 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$225.00	225.00 X
2	FOOT REST FRONT & BODY ALIGNMENT - (REPORTED BY MECHANIC)	Repair	1.00	\$310.00	310.00 X
3	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING & INSTALLATION OF PARTS	Supply/Install	2.00	\$85.00	170.00
4	PROTECTOR EXHAUST P/N: 68051 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$132.00	132.00
5	PROTECTOR EXHAUST CAP P/N: 68052 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$62.00	62.00
6	TRANSPORT CHARGES P/N: 07169 - ONE WAY TOWING		1.00	\$62.00	62.00 X

SUB TOTAL	\$961.00
GST @ 9 %	\$86.49
GRAND TOTAL (SGD)	\$1,047.49

50% deposit required before ordering of parts.

Validity: 30 days

*47899 *

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



bizSAFE₃



2-194
102
174.6
80
254.60
201/2
223

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	For & on Behalf of				Acknowledge & Accepted By
	BAN HOCK HIN CO PTE LTD				



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*47899 *

