

Your Ref : CMTD2403237/GPL(THE)

Date: 01<sup>st</sup> Nov 2024

Our Ref : CS/SMO24100146/Nvh3e2

**M/s Sompo Insurance Singapore PL**

50 Raffles Place #03-03

Singapore Land Tower

Singapore 048623

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKX 1759G  
ACCIDENT ON 06/10/2024**

Instruction was received to inspect the vehicle Reg. No. SKX 1759G. The inspection was conducted on 08/10/2024 at the premises of M/s Kan Fook Sing Motor Workshop, Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758.

The following vehicle information was recorded:

Registration Number	: SKX 1759G
Make/Model	: KIA Sorento 2.4 (A) GDI
Year of Registration	: 2015
Body Colour	: Red
Chassis Number	: KNAPH813MG5139246
Engine Capacity	: 2359 cc

The vehicle caught fire. The cause of fire probably due to short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 30,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 24,999.00)
Nett Liability	<u>S\$ 5,001.00</u> =====

Vehicle Inspected By:



MUHD NAZRIL (NAZ)  
Technical Investigator  
LL.B. (Hons) London



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MII(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.