

SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO.: /20241006/1032	2	LOCATION OF FIRE:	
FIRE REPORTED ON: 06 October	er 2024	Pinevale Condominium, Basement Carpark	
TIME OF CALL: 19:21:29 hrs		2 Tampines Street 73 Singapore 528823	
STATION COVERAGE: Tampines Fire Stat	ion		
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine compartment of a Kia car (SKX1759G) parked at lot 142 at the basement carpark of a condominium.			
METHOD OF EXTINGUISHMENT: By SCDF crew using an internal hose reel water jet and two dry powder fire extinguishers.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating/electrical origin at the engine compartment).			
DAMAGE OBSERVED*: As a result of the fire, the engine compartment of the car was damaged. Other parts of the car sustained heat, smoke and water damage. The structure and contents of the basement 1 carpark including but not limited to the walls, floor, ceilings, pipes, electrical fixtures and other miscellaneous items sustained varying degrees of heat, smoke and water damage.			
3. FATALITY/INJURY INFORMATION			
NAME	NRIC/FIN		DEAD/INJURIES SUSTAINED
NIL	N	IIL	NIL
REPORT ISSUED BY: NICK LI KEJING			

This is a computer generated report. No signature is required.

for COMMISSIONER

SINGAPORE CIVIL DEFENCE FORCE

^{*}This is based on observations made by the fire investigator incidental to his/her investigation to determine the cause and origin of the fire, and is not to be taken as an exhaustive list of damage caused by the fire.