

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24060204/UMA3Q2
Date: 18/06/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002571_01
Claimant Vehicle No : FX5429S Insured Vehicle No : SLF7506M
Date of Loss: 11/06/2024 Nature of Claim: TP Claim No: MFL2024D0007249

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FX5429S
Make & Model: HONDA CB400SF, 399cc Engine No: NC23E2041831
Reg. Date: 27/12/2003 (Man. Year: 2003) Chassis No: NC391043446
Colour: White Odometer: 0 km
Engine Capacity: 399 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60 R17 Rear Tyre Size: 160/60 R17
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,565.80	3,402.00	7,163.80	67.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	600.00	500.00	45.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,665.80	4,002.00	7,663.80	65.69
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	11,665.80	3,200.00	8,465.80	72.57
+ GST 9.00/9.00% (S\$)	1,049.92	288.00	761.92	72.57
Nett Amount (S\$)	12,715.72	3,488.00	9,227.72	72.57
+ Loss of Use (4.0 x S\$20.00/day) (S\$)		80.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		3,595.25		
Global Sum Settlement (S\$)		3,590.00		

INSPECTION

Date of Assignment: 25/06/2024
Date Inspected: 25/06/2024 Inspected At: Erzat Lee Motor Trading Pte Ltd (HQ)
Synergy@KB 25 ,, Kaki Bukit Road 4 #03-37
Singapore 417800
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Sep 2024)	
Parts:	N/A	HONDA CB400SF 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FX5429S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FORK	Repair	1,200.00 F	*- FL
2	1		*FORK T-UNDER BRACKET	Serviceable	800.00 F	*- FL
3	1		*STEERING CONE	Not Necessary	300.00 F	*- FL
4	1		*FRONT DISC BRAKE	Not Necessary	800.00 F	*- FL
5	1		*FRONT TYRE SHAFT	Not Necessary	180.00 F	*- FL
6	1		*FRONT FENDER	Cut	300.00 F	*165.00 FL
7	1		*HANDLE BAR	Bent / Twisted	350.00 F	*300.00 FL
8	1		*HANDLE BALANCER	Cut	150.00 F	*60.00 FL
9	1		*SET MIRROR	Damaged	220.00 F	*180.00 FL
10	1		*CLUTH LEVER	Cut	120.00 F	*120.00 FL
11	1		*IU UNIT	Serviceable	155.80 F	*- FL
12	1		*HEAD LAMP	Cracked	380.00 F	*380.00 FL
13	1		*HEAD LAMP STAY	Bent	280.00 F	*280.00 FL
14	1		*HEAD LAMP BRACKET L	Bent	180.00 F	*80.00 FL
15	1		*SET METER	Broken	1,800.00 F	*1,650.00 FL
16	1		*FUEL TANK	Repair	950.00 F	*- FL
17	1		*CRASH BAR	Cut	450.00 F	*450.00 FL
18	1		*GEAR PEDAL	Bent	200.00 F	*115.00 FL
19	1		*MAINSTAND	Repair	280.00 F	*- FL
20	1		*SIDE STAND	Repair	150.00 F	*- FL
21	1		*EXHAUST PIPE (DAMAGED)	Not Consistent With The Impact	1,200.00 F	*- FL
22	1		*BRAKE LEVER (CUT)	Not Consistent With The Impact	120.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	10,565.80	3,780.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	378.00
Total Parts (\$\$)	10,565.80	3,402.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY COVER	New	500.00	300.00
2	LABOUR	New	600.00	300.00
Gross Labour Cost (S\$)			1,100.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >