

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 24-Jun-24

Estimate no.

1411

Plate No. FX5429S

Model. CB400

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 1,200.00	X	
2	FORK T-UNDER BRACKET	\$ 800.00	X	
3	STEERING CONE	\$ 300.00	X	
4	FRONT DISC BRAKE	\$ 800.00	X	
5	FRONT TYRE SHAFT	\$ 180.00	X	
6	FRONT FENDER	CUT \$ 165 300.00	✓	
7	HANDLE BAR	Bar/In \$ 300 350.00	✓	
8	HANDLE BALANCER	CUT \$ 60 150.00	✓	
9	MIRROR SET	2 x \$ 180 220.00	✓	
10	CLUTH LEVER	CUT \$ 120.00	✓	
11	IU UNIT	SC \$ 155.80	X	
12	HEAD LAMP	CN \$ 380.00	✓	
13	HEAD LAMP STAY	Bar \$ 280.00	✓	
14	HEAD LAMP BRACKET L	Bar \$ 80 180.00	✓	
15	METER SET	3 x \$ 600 1,800.00	✓	
16	FUEL TANK	n \$ 950.00	X	
17	CRASH BAR	CN \$ 450.00	✓	
18	GEAR PEDAL	2 x \$ 115 200.00	✓	
19	MAINSTAND	n \$ 280.00	X	
20	SIDE STAND	n \$ 150.00	X	
21	EXHAUST PIPE	Daye NLS 1,200.00	X 020 Daye	
22	BRAKE LEVER	CN NLS 120.00	X 020 Daye	
23	SPRAY COVER	(100) \$ 500.00	300	
24	LABOUR	(100) \$ 600.00	300	

Less 10% \$ 1,166.58
 \$ 11,665.80
 Sub Total : \$ 10,499.22
 GST 9% \$ 944.93
 Total: \$ 11,444.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Signature:
 Date:

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

Not Authorised
 900866 of
 25/6/24
 2/2 \$3200
 4 days
 1411

P-3760
 101
 3402
 600
 4002
 201
 3201