



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS ALLIED WORLD ASSURANCE COMPANY LTD
(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8TH FLOOR)
MAPLETREE ANSON SINGAPORE 079914

Ref: CS/AWA24100147/Avp3m4

Date: 29/11/2024

Code: AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	5324S (GBF 3111M)	Veh. Inspected	SGB 3000L
Policy No.	BVMTSB0002462400	Coverage	0
Claim No.	CSG24VMTA00002/HLF	Excess	\$0.00
Assign From	HEW LEE FONG	Assign Date	07/10/2024

2. Vehicle Details

Make & Model	TOYOTA ALPHARD HYBRID	C.C	2487
Engine No.	A25A6057963	Year of Reg.	09/04/2024
Chassis No.	JTNACAAH008001703	Colour	BLACK
Odometer	22751 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/65R17	TOYO	6
L/H Front Tyre	225/65R17	TOYO	6
R/H Rear Tyre	225/65R17	TOYO	6
L/H Rear Tyre	225/65R17	TOYO	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/09/2024	Inspection Date	09/10/2024
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days