

ASSIGNMENT

Front: _____ Date: _____

Estn: _____

OD / TP RES / CD RES / EVA / INV / MV

To in Vehicle No: _____

at W/O _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vek: _____

(Policy Condition)

Remark: Tlevch had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGB3000L Yr Regn: 2024 / April

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Alphard Hybrid 2487

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 22751 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTNACAAH608001703

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/65R17
R: 225/65R17

BS / DUN / EXNQA / GY / FS / LIZA / MIC / QHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 09/10/24

Survey held at Bifrost

Des. of Damages: Fri / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AWA

COE Expiry

Estimate given during : Yes (✓)

1st Survey : No ()

MV :

PV :

Nett :

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

3 + RS \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Inve (\$)

Report Format: _____

Report Form / Report Form

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SGB3000L

Make & Model: Toyota Alphard

Chassis number: JTNACAAH008001703

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate <i>Repair</i>	1	\$ 3,158.90
2	Tailgate glass rubber moulding <i>new</i>	1	\$ 304.10
3	Tailgate "HEV" emblem <i>new</i>	1	\$ 84.20
4	Tailgate RH lamp <i>2</i>	1	\$ 1,009.30
5	Tailgate LH lamp	1	\$ 1,009.30
6	Tailgate inner trim board	1	\$ 1,115.20
7	Tailgate inner trim board clips <i>Not</i>	1set	\$ 80.00
8	Tailgate lock <i>new</i>	1	\$ 1,077.20
9	Tailgate lock catch	1	\$ 67.00
10	Tailgate weatherstrip	1	\$ 394.70
11	Tailgate RH side touch sensor	1	\$ 1,184.50
12	Tailgate LH side touch sensor	1	\$ 1,184.50
13	Rear bumper <i>Delint</i>	1	\$ 968.60
14	Rear bumper clips <i>new</i>	1set	\$ 80.00
15	Rear bumper RH towing cover <i>2</i>	1	\$ 70.40
16	Rear bumper LH towing cover <i>new</i>	1	\$ 70.40
17	Rear bumper RH reflector	1	\$ 77.20
18	Rear bumper LH reflector	1	\$ 77.20
19	Rear bumper RH side reverse sensor <i>new</i>	1	\$ 498.20
20	Rear bumper RH centre reverse sensor <i>3 days</i>	1	\$ 498.20
21	Rear bumper LH centre reverse sensor <i>new</i>	1	\$ 498.20
22	Rear bumper LH side reverse sensor <i>new</i>	1	\$ 498.20
23	Rear bumper reverse sensor lock retainers <i>new</i>	4	\$ 144.80
24	Rear bumper reverse sensor holders <i>new</i>	4	\$ 188.50
25	Rear bumper RH side retainer <i>3 set</i>	1	\$ 130.10
26	Rear bumper LH side retainer <i>new</i>	1	\$ 130.10
27	End panel <i>Delint</i>	1	\$ 1,168.30
28	End panel inner garnish <i>Delint</i>	1	\$ 227.00
29	End panel inner garnish clips <i>new</i>	1set	\$ 70.00
30	End RH side panel <i>2</i>	1	\$ 256.70
31	RH taillamp assy	1	\$ 1,192.80
32	RH taillamp panel <i>Not</i>	1	\$ 388.60
33	RH taillamp lock clips	1set	\$ 70.00
34	RH taillamp lower cover <i>new</i>	1	\$ 394.60
35	RH taillamp lower cover retainer	1	\$ 174.30
36	LH taillamp assy	1	\$ 1,192.80
37	LH taillamp panel	1	\$ 388.60
38	LH taillamp lock clips	1set	\$ 70.00

39	LH taillamp lower cover	1	\$	394.60	+
40	LH taillamp lower cover retainer	1	\$	174.30	+
41	Rear RH fender inner trim	1	\$	4,002.90	+
42	Rear RH fender inner trim clips	1set	\$	80.00	+
43	Rear LH fender inner trim	1	\$	4,002.90	+
44	Rear LH fender inner trim clips	1set	\$	80.00	+
45	Rear compartment panel mat cover	1	\$	732.10	+
46	Rear compartment panel mat cover clips	1	\$	80.00	+
47	Rear compartment panel upper board cover	1	\$	1,328.40	+

\$ 31,067.90
 Parts less 25% \$ 7,766.98
 Total: \$ 23,300.93

No.	Special Nett Items	Qty	Amount S\$	
1	Tailgate glass sealant	1	\$ 80.00	+
2	Tailgate glass inner seal	1	\$ 60.00	+
3	End panel joint sealant	1	\$ 80.00	60

Total: \$ 220.00

No.	Labour and painting	Amount S\$	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,600.00	60
2	Spray painting on affected areas and panels	\$ 1,500.00	60
3	Check wiring and lighting system on affected areas	\$ 100.00	30
4	Apply rust coating chemical on affected areas and panels	\$ 80.00	60
5	Remove and refit tailgate glass to assist repair	\$ 220.00	+
6	Remove and refit tailgate reverse camera to assist repair	\$ 120.00	+
7	Remove and replace tailgate inner mechanism to new tailgate	\$ 200.00	+

8	Remove and replace rear bumper reverse sensors to assist repair	\$	120.00
9	Remove and replace rear inner garnish and trims to assist repair	\$	450.00
Total:		\$	2,790.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 23,300.93

Special Nett: \$ 220.00

Labour: \$ 2,790.00

Total: \$ 26,310.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Adm L
1/9 09/10/24
05 Pys