

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-36/37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatileemotor.com

ESTIMATE COST OF REPAIR

Date: 11-Dec-24

Estimate no. 1562

Plate No. FBW6035R

Model.

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	HANDLER BAR	\$ 225.00		
2	MIRRORS	\$ 38.00		
3	BRAKE LEVER RIGHT	\$ 30.00		
4	BALANCER RIGHT	\$ 40.00		
5	THROTTLE CABLE	\$ 110.00		
6	T-FORK	\$ 180.00		
7	FORK SET	\$ 225.00		
8	STEERING CONE	\$ 115.00		
9	GEAR PEDAL	\$ 40.00		
10	FOOTREST RIGHT	\$ 40.00		
11	COVER FOOTREST RIGHT	\$ 60.00		
12	PIPE PROTECTOR MUFFLER	\$ 60.00		
13	BODY ALIGNMENT	\$ 600.00		
14	FRONT FENDLE	\$ 80.00		
15	REFLECTOR	\$ 20.00		
16	RIM HEAD LAMP	\$ 110.00		
17	HEAD LIGHT UNIT	\$ 305.00		
18	CASE HEAD LIGHTS	\$ 80.00		
19	NUMBER PLATE	\$ 10.00		
20	BRAKE PEDAL	\$ 60.00		
21	LABOUR	\$ 600.00		

Less 10% \$ 302.80
 \$ 3,028.00
 Sub Total : \$ 2,725.20
 GST 9% \$ 245.27
 Total: \$ 2,970.47

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.