



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF24100150/Kvp3m4(N)
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1 HEMMANT ROAD SINGAPORE 438675		Date:	02/01/2025
ATTN: LAI PENGCHONG		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YQ 2964U	Veh. Inspected	SLC 6630J
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2024/054 (LK)	Excess (\$)	0.00
Assign From	LAI PENGCHONG	Assign Date	07/10/2024
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104544027	Colour	METALLIC BLACK
Odometer	93993 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55R16	NEXEN	9 mm
L/H Front Tyre	205/55R16	NEXEN	9 mm
R/H Rear Tyre	205/55R16	GOODYEAR	8 mm
L/H Rear Tyre	205/55R16	GOODYEAR	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/09/2024	Inspection Date	08/10/2024
Survey held at	ESTEEM PERFORMANCE PTE LTD 176 SIN MING DRIVE #01-14 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	