

PR1. 7/10/24 @ 15-46

SD



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SLC 6630 J

Parts (a) Cost / List Price Items	<u>\$ 31,940.67</u>
Plus/Less 25%	<u>\$ 7,925.17</u>
Total of Cost / List	<u><u>\$ 23,955.30</u></u>
(b) Nett Price Items	_____
Less	_____
Total of Nett Item	_____
(c) Special Nett Items	_____
Total Parts Cost	<u><u>\$ 23,955.30</u></u>
Labour	<u><u>\$ 5,650.00</u></u>
Total	<u><u>\$ 29,855.50</u></u>

*NOT Authorized
C/Ping &
Murray After Sales*

The above total will be subjected to 9% G.S.T.

Name of Surveyor : Kenneth

Company : UKK

Survey conducted on : 8/10/24 at 11:30

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 10 days day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : *PK* Date: 8/10/24



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : SLC6630J
 Make & Model : TOYOTA COROLLA ALTIS 1.6L CVT
 Chassis No : MR053REH104544027

Submit By : JENNY
 Year Manufacture : 23-May-16
 Engine No. : 1ZRY246617

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH <i>mg cna</i>	1	467.90		✓
2	Front bumper	1	224.30		?
3	Front bumper clip <i>mc</i>	10	50.00		✓
4	Front bumper side retainer LH <i>sm</i>	1	130.70		X
5	Front bumper side retainer RH <i>sm</i>	1	130.80		X
6	RH wing mirror (motor) <i>bcu</i>	1	175.80		✓
7	RH wing mirror (glass)	1			?
8	RH wing mirror signal lamp <i>cm</i>	1			✓
9	RH wing mirror cover <i>mr1</i>	1	152.70		✓
10	RH front fender <i>by</i>	1	137.90		✓
11	RH front fender undershield <i>dis</i>	1	357.50		✓
12	RH front fender undershield clip <i>mc</i>	10	50.00		✓
13	RHF fender top quarter garnish <i>wt</i>	1	61.40		✓
14	RHF fender wording "VVTI" <i>mc</i>	1	44.17		✓
15	RH front lower arm	1	1113.90		?
16	RH front shock absorber	1	676.50		?
17	RH front knuckle arm	1	878.60		?
18	RH front knuckle bearing	1	230.80		?
19	RH front wheel hub	1	307.50		?
20	RH front wheel hub lock nut	1	27.90		?
21	RH front wheel housing <i>k</i>	1	671.50		X
22	RH front rim <i>sm</i>	1	2724.50		X
23	RH front tyre <i>mc</i>	1	\$350.00	S.N	X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLC6630J
 Make & Model : TOYOTA COROLLA ALTIS 1.6L CVT
 Chassis No : MR053REH104544027

Submit By : JENNY
 Year Manufacture : 42513
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH front door	1	1436.10		✓
25	RH front door hinge top	1	135.40		✗
26	RH front door hinge bottom	1	135.40		✗
27	RH front door lock	1	779.30		✓
28	RH front door catch	1	31.70		✗
29	RH front door checker	1	255.50		✗
30	RH front door weatherstip	1	249.10		✓
31	RH front weatherstip (body)	1	405.30		✓
32	RH front door trim	1	1321.70		✓
33	RHF door glass outer moulding	1	191.10		✓
34	RHF power window motor	1	1273.60		✓
35	RHF power window regulator	1	438.60		✓
36	RH rear door	1	1921.10		✓
37	RH rear door hinge top	1	135.40		✗
38	RH rear door hinge bottom	1	135.40		✗
39	RH rear door lock	1	779.30		✓
40	RH rear door catch	1	31.60		✗
41	RH rear door checker	1	255.50		✗
42	RH rear door weatherstip	1	249.10		✓
43	RH rear weatherstip (body)	1	363.10		✓
44	RH rear door trim	1	1031.40		✓
45	RHR door glass outer moulding	1	191.10		✗
46	RHR power window motor	1	981.30		✗

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLC6630J
 Make & Model : TOYOTA COROLLA ALTIS 1.6L CVT
 Chassis No : MR053REH104544027

Submit By : JENNY
 Year Manufacture : 42513
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	RHR power window regulator	1	350.70		?
48	RH rear fender <i>hy</i>	1	175.90		✓
49	RH rear fender mud flap <i>su</i>	1	17.90		X
50	RH rear fender undershield <i>su</i>	1	84.10		X
51	RH rear fender undershield clip <i>su</i>	10	40.00		X
52					
53					
54					
55					
56					
57					
58					
59					
60					
61					
62					
63					
64					
65					
66					
67					
68					
69					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Supplementary

Spare Parts

Vehicle No. : SLC 6630 J
Make & Model : TOYOTA ALTIS
Chassis No : MR053REH104544027

Submit By : JENNY
Year Manufacture : 23-May-16
Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH front door frame	1	\$577.90		By ✓
2	RH front fender inner side garnish	1	\$139.10		CMA ✓
3	RH front door handle	1	\$11.00		Nil ✓
4					
5					
6					
7					
8					
9					
10					
11	Labour Charge:				
12	To renew damaged parts & knock out accident repair area. (RHF door frame)	1	\$400.00		
13					
14	To putty, respray paint for affected accident repair area. (RHF door frame)	1	\$400.00		
15					
16	To remove & refit dashboard to assist work load	1	\$300.00		
17					
18					
19					
20					
21					
22					
23					

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N



ESTEEM

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14 , #01-15 , #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Labour

Vehicle No. : SLC6630J Submit By : JENNY
Make & Model : OTA COROLLA ALTIS 1.6L CVT Year of Manufacture : 23-May-16

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER,RHF FENDER,RHS MIRROR, RHF DOOR,RHR DOOR,RHS ROCKER PANEL,RHR FENDER, REAR BUMPER)	\$2,000.00	1200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,RHF FENDER,RHS MIRROR, RHF DOOR,RHR DOOR,RHS ROCKER PANEL,RHR FENDER, REAR BUMPER)	\$1,800.00	1200
3	To check wiring, focus headlamp	\$50.00	20
4	To remove & refit undercarriage to assist work load.	\$300.00	7
5	To do wheel alignment.	\$120.00	60
6	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$300.00	120
7	To tuff coat.	\$200.00	120
8	To remove & refit inner seat & upholstery to assist work load.	\$200.00	100
9	To remove & refit roof lining, inner trim to assist work load.	\$200.00	
10	To remove & refit rear bootlid to assist work load	~ ~ \$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any

