

ASS. REC. BY:

REF:

SPI

CS/SPF24100150/Kvp3

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Esleem

of 651D

Insured: YQ 2964U

Policy No. \_\_\_\_\_

Claims No. ACS/105/009/2024/054/LK

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 830,500

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLC 8830J Yr Regn: 051 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toy Altis c.c. 1598

Colour: Mr. Black A/C: Insured / Std / NI / NA

Sp. Reading: 93993 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_ C/No: MRO53REH104544027

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rlm / STD A/Rlm or

Tyre Size: F: Nexen 205/55R16

R: Gy

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 9 mm Rear R/Bal. 8 mm

L/Bal. 9 mm L/Bal. 8 mm

D.O.A. 25/9/24 D.O.I. 8/10/2024

Survey held at \_\_\_\_\_ Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or O/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>2/12</u>	<u>11 Rep 811,600</u>
<u>26/12/24</u>	<u>LS \$11,600 confirmed by email (Red 20,734.50, 64%)</u>

Date/Time, File Pass to?  : Prell. Report  : Final Report

1) \_\_\_\_\_ Date/Time, File Return to? 2) \_\_\_\_\_

Report Format : Lump Sum / I.B.I: (\$

Days Of Repair: 10

Resurvey No. of Trip: \_\_\_\_\_

- Add Fee:  : Site Insp (\$
- : Interview (\$
- : Tech Invs (\$
- : Weekend (\$

Survey Fee:	
Transportation:	
S + RS:	\$
Fees:	
Others:	
TOTAL:	

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of First Submission .....	26/09/2024 11:43 (SGT)
Reported by .....	Owner
Date of Accident .....	25/09/2024 09:54 (SGT)
Exact Location of Accident .....	PIE, Singapore
Additional Location Information .....	Towards Tuas
Country/State of Loss .....	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLC6630J

### INSURED/POLICYHOLDER

Is company? .....	Yes
Name Of Registered Owner .....	GOLDBELL CAR RENTAL PTE LTD
Company Reg No .....	2XXXXX651D
Email Address .....	accident@gbcr.com.sg
Mobile Phone No .....	(Phone) +65-66039398
Alternative Phone No .....	-

### VEHICLE PARTICULARS

Manufacturer .....	Toyota
Model .....	Corolla
Variant .....	-
Exact purpose for which vehicle was being used at time of accident .....	Private use
Are you claiming under your own insurance policy for repair to your vehicle? .....	Yes
Vehicle Category .....	Private car
Transmission .....	Auto
CC .....	1598
Vehicle Fuel .....	-
First Registration Date .....	-
Chassis no .....	-
Effective Date/Time of Ownership .....	-

### INSURANCE COMPANY

Name of Insurance Company .....	Tokio Marine Insurance Singapore Ltd
Policy Number / Cover Note Number .....	24-MAB00157-R00

Name of Driver .....	LIM YONG FENG
NRIC No .....	SXXXX747C
Date Of Birth .....	30/12/1993
Occupation .....	Outdoor
Driving Pass Date .....	31/08/2012
Driving License Pass Class .....	3
Driving License Validity .....	Valid
Driving experience .....	12 YEARS AND 1 MONTH
Gender .....	Male
Mobile Number .....	(Phone) +65-91198489
Alt. Phone Number .....	-
Email Address .....	kelvin.lim@oneberry.com
Address .....	BLK 128A PLANTATION CRESCENT #02-423
Address complement .....	-
Postcode .....	691128
Is the driver the policyholder? .....	No
If No, Relationship of the Driver with the Insured .....	Authorised driver
Does Driver Own Other Vehicles? .....	No
Vehicle Registration Number of Other Vehicle Owned by Driver .....	-
Insurance Company of Other Vehicle Owned by Driver .....	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....	Side Swipe
Weather Conditions .....	Clear
Road Surface .....	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....	No
Number of vehicles involved in the accident .....	2
Was anybody injured in the Accident? .....	Yes
Was any injured conveyed to hospital by ambulance? .....	Yes
Was any other vehicle or property damaged? .....	Yes
Number of Passengers (Including Driver) .....	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....	No
Translator's name .....	-
Translator's ID .....	-
Translator's phone number .....	-
Translator's email .....	-
Original language used in the statement .....	-

PASSENGER 1

Name .....	REYNALDO LABAGUIS JR.
Gender .....	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? .....	Yes
Police Station Name .....	Orchard Neighbourhood Police Centre
Police Station Phone No .....	(Phone) +65-18007359999
Alt. Police Station Phone No .....	(Fax) +65-67331934
Police Station Address .....	51 Killiney Road Singapore 239572
Was notice of intended Prosecution given? .....	No
If yes, against whom? .....	-

CIRCUMSTANCES OF ACCIDENT

Please refer to the police report.

ATTACHMENTS

Are accident photos available for attachment? ..... Yes  
 Was there any video captured by Car Camera? ..... Yes  
 Reasons for not uploading a video of the accident ..... The video is with the owner.

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number ..... YQ2964U  
 Vehicle Manufacturer ..... -  
 Vehicle Model ..... -  
 Vehicle Variant ..... -  
 Vehicle Colour ..... -  
 Vehicle Category ..... Government  
 Name of Driver ..... MOHAMED ISKANDAR BIN MOHAMED  
 NRIC No ..... SXXXX220D  
 Contact Number ..... -  
 Address ..... -  
 Address complement ..... -  
 Postcode ..... -  
 Insurance Company Name ..... -  
 Nature Of Damage ..... -  
 Details of property damaged in accident ..... -  
 No. Of Passenger (Including Driver) ..... -

**INJURED PERSONS DETAILS**

INJURED 1

Name of injured person ..... LIM YONG FENG  
 Gender ..... Male  
 Phone No ..... (Phone) +65-91198489  
 Address ..... -  
 Address Complement ..... -  
 Post Code ..... -  
 Approximate Age Years Old ..... -  
 Injuries Sustained ..... -  
 Injured person in which vehicle? ..... SLC6630J  
 Were seat belts worn? ..... -  
 Was this injured conveyed to hospital by ambulance? ..... Yes

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


*Kelvin*  
 26 September 2024  
 0900hrs

Actual Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel  
 (Name as in NRIC/ID card) *SOH JIT HOON*

Sketch Plan



**Describe Circumstance of the Accident**

On 25/09/2024, at about 0954hrs, I was travelling along lane 2 of PIE towards Tuas near exit 17. I was going straight on the road, where one Police SOC vehicle side swiped my car from my right rear passenger side. The impact caused my vehicle to turn 90 degrees, and the head of the truck was at the driver's side. I felt the impact on my right shoulder and left knee, subsequently I was conveyed to Tan Tock Seng Hospital to get treated before the arrival of Traffic Police. I was given 3 days MC.

I observed that my right side view mirror came off, right driver door was crushed and I have to exit from the passenger side. I do not know if there are more damages as I was conveyed shortly after the accident. My passenger was fine and did not require conveyance.

After the accident, I did not witness the driver, it was through his colleagues that I managed to get a photo of the driver's IC and driving license. However they were not willing to pass to me the driver's contact number.

There is a youtube link of the accident: <https://youtu.be/3UFCfja6p3A?si=hW7stMo8T5NbioE3>

**Declaration**

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

 26 September 2024  
0900hrs  
Actual Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card) **SOH JIT HOON**



**SINGAPORE  
POLICE FORCE**



T/20240925/2051

Police Station Of Origin:  
Orchard N.P.C  
51 Killiney Road SINGAPORE 239572  
Tel No: 1800-7359999

1 of 3

Report No. T/20240925/2051

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 25/09/2024 15:49	Vide Report No.: E/20240925/0035	Station Diary No.: 73
--	-------------------------------------	--------------------------

**Informant's Particulars**

Name of Informant: LIM YONG FENG		Address: 128A PLANTATION CRESCENT #02-423 SINGAPORE 691128	
ID Type / ID No.: NRIC NO / S9349747C		Contact No.:	Mobile: 91198489
Nationality: SINGAPORE CITIZEN		Email: limyongfeng@gmail.com	
Sex: Male	Age: 30	Date of Birth: 30/12/1993	Type of Informant: Driver
Race: Chinese		Language: English	
Occupation: Business development manager		Driving Licence Information: Class: 3                      Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 25/09/2024 09:55	Type of Location: Straight Road
Location:  PAN-ISLAND EXPRESSWAY				
Weather: Clear		Road Surface: Dry		
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLC6630J	Motor car				Seriously Damaged	1
YQ2964U	Bus/Coach/Minibus				Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE  
POLICE FORCE



T/20240925/2051

Police Station Of Origin:  
Orchard N.P.C  
51 Killiney Road SINGAPORE 239572  
Tel No: 1800-7359999

2 of 3

Report No. T/20240925/2051

CONTINUATION OF REPORT

Driver			
Name	LIM YONG FENG	ID No.	S9349747C
Related Vehicle	SLC6630J (Motor car)	Contact No.	91198489
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date Treatment	25/09/2024	Date Discharge	25/09/2024
No. of Days granted Medical Leave	03	Degree of	Slight

**Brief Details.**

On 25/09/2024, at about 0954hrs, I was travelling along lane 3 of PIE towards Tuas near exit 17. I was going straight where one SOC vehicle side swiped my car from my right rear passenger side. Subsequently, my vehicle turned 90 degrees, and the head of the truck was at the driver side. I was conscious the whole incident. I was subsequently conveyed to Tan Tock Seng Hospital to get treated before arrival of Traffic Police. I felt impact on my right shoulder and left knee. Doctor informed that there was no fracture. I was given 3days of medical leave.

I observed that my right-side view mirror came off, right driver's door was crushed. I do not know if there are more damages as I was conveyed shortly after the accident. My passenger was fine and did not require conveyance.

There is a YouTube link: <https://youtu.be/3UFCfja6p3A?si=ApblPlzZ1AnY42g>

Passenger name: Rey  
HP: 89008331



SINGAPORE  
POLICE FORCE



T/20240925/2051

Police Station Of Origin:  
Orchard N.P.C  
51 Killiney Road SINGAPORE 239572  
Tel No: 1800-7359999

3 of 3

Report No. T/20240925/2051

CONTINUATION OF REPORT

Signature of Officer Recording The  
E /  
SGT 2 LIM JUN JIE

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
25/09/2024 15:49

Officer In Charge Of Case:  
TP / GIT /  
ASP (1) YAP ENG SIANG  
Contact No.: 96324893

Classification Of Case:

NP168

SPF

PR1 = 7/10/24 @ 15=46

SD



**ESTEEM**

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

**Repair Estimates**

SLC 6630 J

<b>Parts</b>	(a) Cost / List Price Items	_____
	Plus/Less <u>25%</u>	_____
	<b>Total of Cost / List</b>	=====
	(b) Nett Price Items	_____
	Less _____	_____
	<b>Total of Nett Item</b>	_____
	(c) Special Nett Items	_____
<b>Total Parts Cost</b>		=====
<b>Labour</b>	<b>\$</b>	<b>5,650.00</b>
<b>Total</b>		=====

*NOT Authorized  
L1 Rep &  
Survey After Paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

The above total will be subjected to 9% G.S.T.

Name of Surveyor	:	<u>Kenneth</u>
Company	:	<u>LKK</u>
Survey conducted on	:	<u>8/10/24</u> at <u>11:30</u>
<u>Remarks By Surveyor</u>		
(a) The repair of this vehicle is <del>not</del> authorized / is not authorized until further notice.		
(b) Recommended Days of Repair	:	<u>10 days</u> day(s)
(c) Resurvey	:	Required / Not Required <u>Not Required</u>
(d) Excess	:\$	_____
(e) Signature of surveyor	:	<u>[Signature]</u> Date: <u>8/10/24</u>



# ESTEEM

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

**HEADQUARTERS / SHOWROOM / WORKSHOP**

385 Sin Ming Drive  
Singapore 575718

(T) 6753 2112 (F) 6451 0394

**WORKSHOP**

176 Sin Ming Drive

Sin Ming Auto Care #01-14, #01-15, #01-16

Singapore 575721

(T) 6484 1221 (F) 6484 7829

**Spare Parts**

Vehicle No. : SLC6630J  
Make & Model : TOYOTA COROLLA ALTIS 1.6L CVT  
Chassis No : MR053REH104544027

Submit By : JENNY  
Year Manufacture : 23-May-16  
Engine No. : 1ZRY246617

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH <i>my CM</i>	1			✓
2	Front bumper <i>su</i>	1			X
3	Front bumper clip <i>me</i>	10			✓
4	Front bumper side retainer LH <i>su</i>	1			X
5	Front bumper side retainer RH <i>su</i>	1			X
6	RH wing mirror (motor) <i>BU</i>	1			✓
7	RH wing mirror (glass) <i>su</i>	1			X
8	RH wing mirror signal lamp <i>CM</i>	1			✓
9	RH wing mirror cover <i>MVJ</i>	1			✓
10	RH front fender <i>By</i>	1			✓
11	RH front fender undershield <i>D/S</i>	1			✓
12	RH front fender undershield clip <i>me</i>	10			✓
13	RHF fender top quarter garnish <i>CV</i>	1			✓
14	RHF fender wording "VVTI" <i>me</i>	1			✓
15	RH front lower arm <i>su</i>	1			X
16	RH front shock absorber <i>su</i>	1			X
17	RH front knuckle arm <i>su</i>	1			X
18	RH front knuckle bearing <i>nu</i>	1			X
19	RH front wheel hub <i>su</i>	1			X
20	RH front wheel hub lock nut <i>su</i>	1			X
21	RH front wheel housing <i>K</i>	1			X
22	RH front rim <i>su</i>	1			X
23	RH front tyre <i>su</i>	1	\$350.00	S.N	X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. : **SLC6630J**  
 Make & Model : **TOYOTA COROLLA ALTIS 1.6L CVT**  
 Chassis No : **MR053REH104544027**

Submit By : **JENNY**  
 Year Manufacture : **42513**  
 Engine No. :

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH front door	1			✓
25	RH front door hinge top	1			✓
26	RH front door hinge bottom	1			✓
27	RH front door lock	1			✓
28	RH front door catch	1			X
29	RH front door checker	1			X
30	RH front door weatherstip	1			?
31	RH front weatherstip (body)	1			?
32	RH front door trim	1			?
33	RHF door glass outer moulding	1			✓
34	RHF power window motor	1			?
35	RHF power window regulator	1			?
36	RH rear door	1			✓
37	RH rear door hinge top	1			X
38	RH rear door hinge bottom	1			X
39	RH rear door lock	1			?
40	RH rear door catch	1			X
41	RH rear door checker	1			X
42	RH rear door weatherstip	1			?
43	RH rear weatherstip (body)	1			?
44	RH rear door trim	1			?
45	RHR door glass outer moulding	1			X
46	RHR power window motor	1			X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. : SLC6630J  
 Make & Model : TOYOTA COROLLA ALTIS 1.6L CVT  
 Chassis No : MR053REH104544027

Submit By : JENNY  
 Year Manufacture : 42513  
 Engine No. : \_\_\_\_\_

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	RHR power window regulator	1			?
48	RH rear fender <i>Hy</i>	1			✓
49	RH rear fender mud flap <i>Sn</i>	1			X
50	RH rear fender undershield <i>Sn</i>	1			X
51	RH rear fender undershield clip <i>nn</i>	10			X
52					
53					
54					
55					
56					
57					
58					
59					
60					
61					
62					
63					
64					
65					
66					
67					
68					
69					

*Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.*



# ESTEEM

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

## Labour

Vehicle No. : SLC6630J Submit By : JENNY  
Make & Model : TOYOTA COROLLA ALTIS 1.6L CVT Year of Manufacture : 23-May-16

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER,RHF FENDER,RHS MIRROR, RHF DOOR,RHR DOOR,RHS ROCKER PANEL,RHR FENDER, REAR BUMPER)	\$2,000.00	1200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,RHF FENDER,RHS MIRROR, RHF DOOR,RHR DOOR,RHS ROCKER PANEL,RHR FENDER, REAR BUMPER)	\$1,800.00	1200
3	To check wiring, focus headlamp	\$50.00	20
4	To remove & refit undercarriage to assist work load.	\$300.00	7
5	To do wheel alignment.	\$120.00	60
6	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$300.00	120
7	To tuff coat.	\$200.00	120
8	To remove & refit inner seat & upholstery to assist work load.	\$200.00	100
9	To remove & refit roof lining, inner trim to assist work load.	\$200.00	
10	To remove & refit rear bootlid to assist work load	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any



PR1 - 7/10/24 @ 15-46

SD



# ESTEEM

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6763 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

### Repair Estimates

SLC 6630 J

Parts (a) Cost / List Price Items	\$ 31,940.67
Plus/Less 25%	\$ 7,925.17
<b>Total of Cost / List</b>	<b>\$ 23,955.30</b>
(b) Nett Price Items	_____
Less	_____
<b>Total of Nett Item</b>	_____
(c) Special Nett Items	_____
<b>Total Parts Cost</b>	<b>\$ 23,955.30</b>
Labour	\$ 5,650.00
<b>Total</b>	<b>\$ 29,605.30</b>

*Not Authorized  
C/P Rep \$11,600/h  
Resurvey After Pains*

The above total will be subjected to 9% G.S.T.

Name of Surveyor : Kenneth

Company : UIC

Survey conducted on : 8/10/24 at 11:30

#### Remarks By Surveyor

(a) The repair of this vehicle is not authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 10 days day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : [Signature] Date: 8/10/24



# ESTEEM

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

### Spare Parts

Vehicle No. : SLC6630J  
Make & Model : TOYOTA COROLLA ALTIS 1.6L CVT  
Chassis No : MR053REH104544027

Submit By : JENNY  
Year Manufacture : 23-May-16  
Engine No. : 1ZRY246617

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH 3243.20 <i>mg CM</i>	1	467.90		✓
2	Front bumper <i>sm</i>	1	224.30		X
3	Front bumper clip <i>me</i>	10	60.00		✓
4	Front bumper side retainer LH <i>sm</i>	1	130.80		X
5	Front bumper side retainer RH <i>sm</i>	1	130.80		X
6	RH wing mirror (motor) 1258.60 <i>BC</i>	1	1752.20		✓
7	RH wing mirror (glass)	1			X
8	RH wing mirror signal lamp <i>CM</i>	1			✓
9	RH wing mirror cover <i>mr</i>	1	152.90		✓
10	RH front fender 782 <i>By</i>	1	1326.90		✓
11	RH front fender undershield 215.30 <i>dis</i>	1	357.50		✓
12	RH front fender undershield clip <i>me</i>	10	50.00		✓
13	RHF fender top quarter garnish <i>wt</i>	1	61.40		✓
14	RHF fender wording "VVTI" <i>me</i>	1	44.17		✓
15	RH front lower arm <i>sm</i>	1	1113.90		X
16	RH front shock absorber <i>sm</i>	1	676.50		X
17	RH front knuckle arm <i>sm</i>	1	878.60		X
18	RH front knuckle bearing <i>nn</i>	1	230.80		X
19	RH front wheel hub <i>sm</i>	1	362.50		X
20	RH front wheel hub lock nut <i>sm</i>	1	27.90		X
21	RH front wheel housing <i>rc</i>	1	671.50		X
22	RH front rim <i>sm</i>	1	2724.50		X
23	RH front tyre <i>me</i>	1	\$350.00	S.N	X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

585657

**Spare Parts**

Vehicle No. : SLC6630J  
 Make & Model : TOYOTA COROLLA ALTIS 1.6L CVT  
 Chassis No : MR053REH104544027

Submit By : JENNY  
 Year Manufacture : 42513  
 Engine No. : \_\_\_\_\_

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH front door 1665-20 R <sub>1</sub>	1	1436.10		✓
25	RH front door hinge top 108-10 R <sub>1</sub>	1	135.40		⊗
26	RH front door hinge bottom 108-10 R <sub>1</sub>	1	135.40		⊗
27	RH front door lock 481-50 R <sub>1</sub>	1	779.30		⊗
28	RH front door catch R	1	31.70		⊗
29	RH front door checker 152-80 Dis R <sub>1</sub>	1	255.50		⊗
30	RH front door weatherstip R <sub>1</sub>	1	249.10		⊗
31	RH front weatherstip (body) R <sub>1</sub>	1	405.30		⊗
32	RH front door trim 915-20 R <sub>1</sub> COM	1	1321.70		⊗
33	RHF door glass outer moulding R <sub>1</sub>	1	191.10		✓
34	RHF power window motor 612-20 R <sub>1</sub>	1	1273.60		⊗
35	RHF power window regulator 304 Dis R <sub>1</sub>	1	432.60		⊗
36	RH rear door 1521-60 R <sub>1</sub>	1	1921.10		✓
37	RH rear door hinge top R	1	135.40		⊗
38	RH rear door hinge bottom R	1	135.40		⊗
39	RH rear door lock R	1	779.30		⊗
40	RH rear door catch R	1	31.60		⊗
41	RH rear door checker R	1	255.50		⊗
42	RH rear door weatherstip R <sub>1</sub>	1	249.10		⊗
43	RH rear weatherstip (body) R <sub>1</sub>	1	363.10		⊗
44	RH rear door trim R <sub>1</sub>	1	1031.40		⊗
45	RHR door glass outer moulding R <sub>1</sub>	1	191.10		⊗
46	RHR power window motor R <sub>1</sub>	1	981.30		⊗

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. : SLC6630J  
 Make & Model : TOYOTA COROLLA ALTIS 1.6L CVT  
 Chassis No : MR053REH104544027

Submit By : JENNY  
 Year Manufacture : 42513  
 Engine No. :

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	RHR power window regulator	1	350.70		X
48	RH rear fender 1471.10	1	1765.90		✓
49	RH rear fender mud flap	1	67.90		X
50	RH rear fender undershield	1	84.10		X
51	RH rear fender undershield clip	10	40.00		X
52					
53					
54					
55					
56					
57					
58					
59					
60					
61					
62					
63					
64					
65					
66					
67					
68					
69					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



**ESTEEM**

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

Labour

Vehicle No. : SLC6630J Submit By : JENNY  
Make & Model : DTA COROLLA ALTIS 1.6L CVT Year of Manufacture : 23-May-16

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER,RHF FENDER,RHS MIRROR, RHF DOOR,RHR DOOR,RHS ROCKER PANEL,RHR FENDER, REAR BUMPER)	\$2,000.00	1300
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,RHF FENDER,RHS MIRROR, RHF DOOR,RHR DOOR,RHS ROCKER PANEL,RHR FENDER, REAR BUMPER)	\$1,800.00	1800
3	To check wiring, focus headlamp	\$50.00	20
4	To remove & refit undercarriage to assist work load. <i>mm</i>	\$300.00	X
5	To do wheel alignment.	\$120.00	60
6	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$300.00	120
7	To tuff coat.	\$200.00	120
8	To remove & refit inner seat & upholstery to assist work load.	\$200.00	100
9	To remove & refit roof lining, inner trim to assist work load.	\$200.00	
10	To remove & refit rear bootlid to assist work load <i>mm</i>	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any





ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

## Supplementary

### Spare Parts

Vehicle No. : \_\_\_\_\_  
Make & Model : SLC 6630 J  
Chassis No : TOYOTA ALTIS  
MR053REH104544027

Submit By : \_\_\_\_\_  
Year Manufacture : JENNY  
Engine No. : 23-May-16

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH front door frame	1	\$577.90		By ✓
2	RH front fender inner side garnish	1	\$139.10		CMA ✓
3	RH front door handle 468.40	1	\$ (1) .00		na ✓
4					
5					
6					
7					
8					
9					
10					
11	Labour Charge:				
12	To renew damaged parts & knock out accident repair area. (RHF door frame)	1	\$400.00		X
13	To putty, respray paint for affected accident repair area. (RHF door frame)	1	\$400.00		X
14	To remove & refit dashboard to assist work load	1	\$300.00		250/
15					
16					
17					
18					
19					
20					
21					
22					
23					