

last Synchroniser  
 J GF CVT (A) (Ca  
 nated Standard  
 0/08/03/2023 22  
 they contain the  
 cer on the last  
 logue are pref

ASS. REC. BY:

REF:

*SPI*

*Kenneth*

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s *Estee*

of *6510*

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *830k*

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: *10* days Res.: Yes or No

Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: *SLC 6630J* Yr Regn: *051 16*

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: *Toy Altis* cc *1598*

Colour: *h. Black* A/C: Insured / Std / NI / NA

Sp. Reading: *93993* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *MRO53REH104544027*

Gen. Conhd:  Good /  Fair /  Poor /  Burnt

Steering:  Inorder /  Jammed /  Leaked /  Burnt or

Brake:  Inorder /  Jammed /  Leaked /  Burnt or

Modf: NII / S/Rlm / STD A/Rlm or

Tyre Size: F: *Nexen 205/55R16*

R: *Gy*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

R/Bal. *9* mm

L/Bal. *9* mm

D.O.A. *25/9/24*

Rear

R/Bal. *8* mm

L/Bal. *8* mm

D.O.I. *8/10/2024*

Survey held at \_\_\_\_\_

Des. of Damages:  Frt /  Rear /  O/S /  N/S /  UIC /  Rooftop or

*o/s body*

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: \_\_\_\_\_

1) \_\_\_\_\_  
Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Transportation

\$ - RS. \$ \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)


**ASSIGNMENT**

PR1 = 7/10/24 @ 15:46

SD :

SPF



**ESTEEM**

**ESTEEM PERFORMANCE PTE LTD**  
UEN 200006486N

**HEADQUARTERS / SHOWROOM / WORKSHOP**  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

**WORKSHOP**  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

**Repair Estimates**

SLC 6630 J

*Not Authorized  
L1 Rep &  
Resurvey After Paint*

<b>Parts</b>	(a) Cost / List Price Items	_____
	Plus/Less 25%	_____
	<b>Total of Cost / List</b>	=====
	(b) Nett Price Items	_____
	Less	_____
	<b>Total of Nett Item</b>	_____
	(c) Special Nett Items	_____
<b>Total Parts Cost</b>		=====
<b>Labour</b>		\$ <u>5,650.00</u>
<b>Total</b>		=====

The above total will be subjected to 9% G.S.T.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 8/10/24 at 11:30

**Remarks By Surveyor**

(a) The repair of this vehicle is not authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 10 days day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : [Signature] Date: 8/10/24



**ESTEEM**

ESTEEM PERFORMANCE PTE LTD  
UEN 200008485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

**Spare Parts**

Vehicle No. : SLC6630J  
Make & Model : TOYOTA COROLLA ALTIS 1.6L CVT  
Chassis No : MR053REH104544027

Submit By : JENNY  
Year Manufacture : 23-May-16  
Engine No. : 1ZRY246617

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH <i>My car</i>	1			✓
2	Front bumper	1			?
3	Front bumper clip <i>me</i>	10			✓
4	Front bumper side retainer LH <i>in</i>	1			X
5	Front bumper side retainer RH <i>in</i>	1			X
6	RH wing mirror (motor) <i>Br</i>	1			✓
7	RH wing mirror (glass)	1			?
8	RH wing mirror signal lamp <i>CM</i>	1			✓
9	RH wing mirror cover <i>Mrs</i>	1			✓
10	RH front fender <i>By</i>	1			✓
11	RH front fender undershield <i>D/S</i>	1			✓
12	RH front fender undershield clip <i>me</i>	10			✓
13	RHF fender top quarter garnish <i>W</i>	1			✓
14	RHF fender wording "VVTI" <i>me</i>	1			✓
15	RH front lower arm	1			?
16	RH front shock absorber	1			?
17	RH front knuckle arm	1			?
18	RH front knuckle bearing	1			?
19	RH front wheel hub	1			?
20	RH front wheel hub lock nut	1			?
21	RH front wheel housing <i>K</i>	1			X
22	RH front rim <i>PL</i>	1			X
23	RH front tyre <i>me</i>	1	\$350.00	S.N	X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. : **SLC6630J**  
 Make & Model : **TOYOTA COROLLA ALTIS 1.6L CVT**  
 Chassis No : **MR053REH104544027**

Submit By : **JENNY**  
 Year Manufacture : **42513**  
 Engine No. :

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH front door	1			✓
25	RH front door hinge top	1			X
26	RH front door hinge bottom	1			X
27	RH front door lock	1			?
28	RH front door catch	1			X
29	RH front door checker	1			X
30	RH front door weatherstip	1			?
31	RH front weatherstip (body)	1			?
32	RH front door trim	1			?
33	RHF door glass outer moulding	1			✓
34	RHF power window motor	1			?
35	RHF power window regulator	1			?
36	RH rear door	1			✓
37	RH rear door hinge top	1			X
38	RH rear door hinge bottom	1			X
39	RH rear door lock	1			?
40	RH rear door catch	1			X
41	RH rear door checker	1			X
42	RH rear door weatherstip	1			?
43	RH rear weatherstip (body)	1			?
44	RH rear door trim	1			?
45	RHR door glass outer moulding	1			X
46	RHR power window motor	1			X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. : SLC6630J  
 Make & Model : TOYOTA COROLLA ALTIS 1.6L CVT  
 Chassis No : MR053REH104544027

Submit By : JENNY  
 Year Manufacture : 42513  
 Engine No. : \_\_\_\_\_

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	RHR power window regulator	1			?
48	RH rear fender <i>sn</i>	1			✓
49	RH rear fender mud flap <i>sn</i>	1			X
50	RH rear fender undershield <i>sn</i>	1			X
51	RH rear fender undershield clip <i>sn</i>	10			X
52					
53					
54					
55					
56					
57					
58					
59					
60					
61					
62					
63					
64					
65					
66					
67					
68					
69					

*Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.*



# ESTEEM

ESTEEM PERFORMANCE PTE LTD  
UEN 200006485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

### Labour

Vehicle No. : SLC6630J Submit By : JENNY  
Make & Model : OTA COROLLA ALTIS 1.6L CVT Year of Manufacture : 23-May-16

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER,RHF FENDER,RHS MIRROR, RHF DOOR,RHR DOOR,RHS ROCKER PANEL,RHR FENDER, REAR BUMPER)	\$2,000.00	1200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,RHF FENDER,RHS MIRROR, RHF DOOR,RHR DOOR,RHS ROCKER PANEL,RHR FENDER, REAR BUMPER)	\$1,800.00	1200
3	To check wiring, focus headlamp	\$50.00	20
4	To remove & refit undercarriage to assist work load.	\$300.00	7
5	To do wheel alignment.	\$120.00	60
6	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$300.00	120
7	To tuff coat.	\$200.00	120
8	To remove & refit inner seat & upholstery to assist work load.	\$200.00	100
9	To remove & refit roof lining, inner trim to assist work load.	\$200.00	
10	To remove & refit rear bootlid to assist work load	~ \$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of First Submission .....	26/09/2024 11:43 (SGT)
Reported by .....	Owner
Date of Accident .....	25/09/2024 09:54 (SGT)
Exact Location of Accident .....	PIE, Singapore
Additional Location Information .....	Towards Tuas
Country/State of Loss .....	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLC6630J

### INSURED/POLICYHOLDER

Is company? .....	Yes
Name Of Registered Owner .....	GOLDBELL CAR RENTAL PTE LTD
Company Reg No .....	2XXXXX651D
Email Address .....	accident@gbcr.com.sg
Mobile Phone No .....	(Phone) +65-66039398
Alternative Phone No .....	-

### VEHICLE PARTICULARS

Manufacturer .....	Toyota
Model .....	Corolla
Variant .....	-
Exact purpose for which vehicle was being used at time of accident .....	Private use
Are you claiming under your own insurance policy for repair to your vehicle? .....	Yes
Vehicle Category .....	Private car
Transmission .....	Auto
CC .....	1598
Vehicle Fuel .....	-
First Registration Date .....	-
Chassis no .....	-
Effective Date/Time of Ownership .....	-

### INSURANCE COMPANY

Name of Insurance Company .....	Tokio Marine Insurance Singapore Ltd
Policy Number / Cover Note Number .....	24-MAB00157-R00

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GI&A Records Management Centre established by the General Insurance Association of Singapore (GI&A) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GI&A") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GI&A to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


*Kehar*  
 26 September 2024  
 0900hrs

Actual Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel  
 (Name as in NRIC/ID card) *SOH JIT HOON*

**Sketch Plan**





**SINGAPORE  
POLICE FORCE**



T/20240925/2051

Police Station Of Origin:  
Orchard N.P.C  
51 Killiney Road SINGAPORE 239572  
Tel No: 1800-7359999

2 of 3

Report No. T/20240925/2051

**CONTINUATION OF REPORT**

Driver			
Name	LIM YONG FENG	ID No.	S9349747C
Related Vehicle	SLC6630J (Motor car)	Contact No.	91198489
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date Treatment	25/09/2024	Date Discharge	25/09/2024
No. of Days granted Medical Leave	03	Degree of	Slight

**Brief Details.**

On 25/09/2024, at about 0954hrs, I was travelling along lane 3 of PIE towards Tuas near exit 17. I was going straight where one SOC vehicle side swiped my car from my right rear passenger side. Subsequently, my vehicle turned 90 degrees, and the head of the truck was at the driver side. I was conscious the whole incident. I was subsequently conveyed to Tan Tock Seng Hospital to get treated before arrival of Traffic Police. I felt impact on my right shoulder and left knee. Doctor informed that there was no fracture. I was given 3days of medical leave.

I observed that my right-side view mirror came off, right driver's door was crushed. I do not know if there are more damages as I was conveyed shortly after the accident. My passenger was fine and did not require conveyance.

There is a YouTube link: <https://youtu.be/3UFCfja6p3A?si=ApbldPlzZ1AnY42g>

Passenger name: Rey  
HP: 89008331