



ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Supplementary

Spare Parts

Vehicle No. : _____
Make & Model : SLC 6630 J
Chassis No : TOYOTA ALTIS
MR053REH104544027

Submit By : _____
Year Manufacture : JENNY
Engine No. : 23-May-16

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH front door frame	1	\$577.90		By ✓
2	RH front fender inner side garnish	1	\$139.10		CMA ✓
3	RH front door handle 468.40	1	\$ (1) .00		na ✓
4					
5					
6					
7					
8					
9					
10					
11	Labour Charge:				
12	To renew damaged parts & knock out accident repair area. (RHF door frame)	1	\$400.00		X
13	To putty, respray paint for affected accident repair area. (RHF door frame)	1	\$400.00		X
14	To remove & refit dashboard to assist work load	1	\$300.00		250/
15					
16					
17					
18					
19					
20					
21					
22					
23					