

# HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

## ESTIMATE

VEHICLE NO : SMA 1709 Z

CHASSIS NO : GP71208328

MAKE / MODEL : HONDA SHUTTLE

ACCIDENT DATE : 29.09.2024

| NO                | DESCRIPTION                                  | QTY                    | AMOUNT (\$)        |
|-------------------|--|------------------------|--------------------|
| <b>LIST ITEMS</b> |  | <b>(QUY's marking)</b> |                    |
| 1                 | Rear tailgate windscreen moulding <i>new</i> | 1                      | \$ 240.00 ✓        |
| 2                 | Rear tailgate <i>Dented</i>                  | 1                      | \$ 1459.00 ✓ 1193  |
| 3                 | Rear tailgate inner board <i>new</i>         | 1                      | \$ 698.00 +        |
| 4                 | Rear tailgate damper @ \$189.50 <i>3 of</i>  | 2                      | \$ 379.00 +        |
| 5                 | Rear tailgate hinge @ \$42.00 <i>2 of</i>    | 2                      | \$ 84.00 +         |
| 6                 | Rear tailgate upper lock <i>2 of</i>         | 1                      | \$ 238.60 ✓        |
| 7                 | Rear tailgate switch <i>new</i>              | 1                      | \$ 179.60 +        |
| 8                 | Rear tailgate weather strip <i>at</i>        | 1                      | \$ 210.30 ✓        |
| 9                 | Rear tailgate H logo <i>new</i>              | 1                      | \$ 60.50 +         |
| 10                | Rea tailgate SHUTTLE emblem <i>new</i>       | 1                      | \$ 60.50 ✓         |
| 11                | Rear end panel <i>Parts</i>                  | 1                      | \$ 590.80 ✓        |
| 12                | Rear end panel top garnish <i>Dented</i>     | 1                      | \$ 165.50 ✓        |
| 13                | Rear bumper <i>Dented</i>                    | 1                      | \$ 1189.00 ✓ 985   |
| 14                | Rear bumper side holder @ \$61.35 <i>new</i> | 2                      | \$ 122.70 +        |
| 15                | Rear bumper clips <i>new</i>                 | 1                      | \$ 50.00 ✓ 30      |
| 16                | Rear tailgate HYBRID emblem <i>new</i>       | 1                      | \$ 60.50 ✓         |
| 17                | Rear bumper reverse sensor <i>new</i>        | 1                      | \$ 380.00 ✓        |
| 18                | Company sticker <i>new</i>                   | 1                      | \$ 120.00 ✓ 100/50 |
|                   |  |                        | \$ 6288.00         |
| LESS 20% DISC     |  |                        | \$ 1257.6          |
| TOTAL             |  |                        | \$ 5030.40         |

### LABOUR COST

|             |   |   |                  |
|-------------|---|---|------------------|
| 1           | To supply rear windscreen sealant                   | 1 | \$ 50.00 ✓       |
| 2           | Remove + reinstall rear windscreen                  | 1 | \$ 200.00 ✓ 120  |
| 3           | Remove + reinstall reverse sensor                   | 1 | \$ 150.00 ✓ 50   |
| 4           | Remove + reinstall bootlid inner garnish            | 1 | \$ 200.00 ✓ 60   |
| 5           | Remove, replace + repair consistent to the accident | 1 | \$ 1000.00 ✓ 500 |
| 6           | Respray painting                                    | 1 | \$ 1000.00 ✓ 260 |
| TOTAL       |   |   | \$ 2600.00       |
| GRAND TOTAL |   |   | \$ 7630.40       |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Adrian  
2/8 14/10/24  
04 Days.