

Kok Wang Car Grooming
1 Soon Lee Street #06-40 Pioneer Centre
Singapore 627605
Hp: 91839633 E-mail: vianong@ymail.com

ESTIMATE REPORT

Vehicle Number : SMS1409U
 Make And Model : Volvo S60 T4
 Date of Accident : 30 September 2024

S/No	Parts	QTY	Unit Price	List Price
1	Rear bumper	1		\$1800 2,121.00 <i>de</i>
2	Rear bumper lower molding	1		\$520 696.90 <i>cut</i>
3	Rear bumper tow cover	1		\$ 60.50 <i>X nn</i>
4	Rear bumper reflector RH	1		\$205 282.80 <i>cut</i>
5	Rear bumper reverse sensor RH	2	\$ 235.00	\$ 470.00 <i>X nn</i>
6	Rear bumper reverse sensor O-ring	6	\$ 18.00	\$ 108.00 <i>rec</i>
7	Rear bumper retainer RH	1		\$ 131.90 <i>X</i>
8	Rear bumper center support	1		\$ 265.00 <i>X nn</i>
9	Rear bumper reinforcement	1		\$ 753.50 <i>X</i>
10	Rear taillamp RH	1		\$840 949.40 <i>cut</i>
				\$ 5,839.00
				Less 10% \$ 583.90
				Total \$ 5,255.10

10% 3473
3125.70

Special Nett Item

1	Rear bumper clips	1 set	\$ 60.00 <i>40mm</i>
			Total \$ 60.00 <i>40</i>

Labour & Misc Charges

To dismantle, replace & panel beating affected parts for rear portion.	\$	800.00	400
To spray paint on affected areas for rear portion.	\$	600.00	500
To remove/replace/reinstall reverse sensors.	\$	80.00	40
To check wiring for rear portion.	\$	60.00	30
To apply anti-rust on affected areas.	\$	60.00	200
To perform system diagnostic & reset ECU system.	\$	300.00	200

Taufik 97445749/62563561453350

WP' 16/12/24 05pm

L/S Resury after repair

taufik e/khanan

3 days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: