Kok Wang Car Grooming 1 Soon Lee Street #06-40 Pioneer Centre Singapore 627605

Hp: 91839633 E-mail: vianong@ymail.com

ESTIMATE REPORT

Vehicle Number: SMS1409U Make And Model: Volvo S60 T4 Date of Accident: 30 September 2024

C/NI-						
S/No	Parts	QTY	Uı	nit Price		List Price
2	Rear bumper	1			\$	2,121.00 de
3	Rear bumper lower molding	1			\$	696.90 cut
4	Rear bumper tow cover	1			\$	60.50X
5	Rear bumper reflector RH	1			\$	282.80 cmg
6	Rear bumper reverse sensor RH	2	\$	235.00	\$	470.00 ×
7	Rear bumper reverse sensor O-ring	6	\$	18.00	\$	108.00 rec
8	Rear bumper retainer RH	1			\$	131.90 ×
9	Rear bumper center support	1			\$	265.00 ⊀
10	Rear bumper reinforcement	1			\$	753.50×
10	Rear taillamp RH	1			\$	949.40 04
					\$	5,839.00
			I	Less 10%	_\$	583.90
				Total	_\$	5,255.10
	Special Nett Items					
1	Special Nett Item					40mer
1	Rear bumper clips	1 set			\$	60.00
				Total	\$	60.00
	Labour & Misc Charges To dismantle, replace & panel beating affected parts for rear porton. To spray paint on affected areas for rear portion. To remove/replace/reinstall reverse sensors. To check wiring for rear portion. To apply anti-rust on affected areas. To perform system diagnostic & reset ECU system. Taufikh 97495749/6236366 Wl' 16/12/24 85pw L/S Resum after porton. Lafikh 97495749/6236366 Wl' 16/12/24 85pw L/S Resum after porton. Janfikh 9/464966 Janfikh 9/464966 Janfikh 9/4649666 Janfikh 9/46496666 Janfikh 9/4649666666666666666666666666666666666	LKk the • To : • To : • Par • Thir • No ii • Suppi	Auto (Repaire resurvey display displa	Duitom(a)	hence Dwing ray pai during confirm Vithout allowed	: nting resurvey ation Prejudice* basis