

SIN YU SIN WORKSHOP

1 KAKI BUKIT AVENUE 6
#01-82 AUTOBAY SINGAPORE 417883

TO	: LIBERTY	DATE	8/10/2024
VEHICLE NO	: SLC7081L (2022)		
VEHICLE MODEL	: MAZDA 3 HYBRID		
CHASSIS NO	: JM6BP2SAAN1150852		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>form</i> X repair	1	\$ 1,143.50	\$ 1,143.50
2	REAR BUMPER SIDE HOLDER <i>new</i>	1	\$ 69.80	\$ 69.80
3	REAR FENDER <i>Repis</i>	1	\$ 1,643.90	\$ 1,643.90
4	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 165.90	\$ 165.90
5	REAR DOOR <i>Derked</i>	1	\$ 1,286.20	\$ 1,286.20
6	REAR DOOR LOCK <i>341</i>	1	\$ 365.90	\$ 365.90
7	REAR DOOR WEATHERSTRIPE <i>341</i>	1	\$ 175.80	\$ 175.80
8	REAR WHEEL RIM <i>lit</i>	1	\$ 1,264.10	\$ 1,264.10
9	REAR AXLE <i>new</i>	1	\$ 2,459.40	\$ 2,459.40
10	REAR WHEEL HUB C/W BEARING <i>new</i>	1	\$ 461.70	\$ 461.70
11	REAR SHOCK ABSORBER <i>new</i>	1	\$ 369.50	\$ 369.50

TOTAL PRICE: \$ 9,405.70
LESS 20% \$ 1,881.14
SUB TOTAL PRICE: \$ 7,524.56

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i> X not nec	1 SET	\$ 50.00	\$ 50.00
2	REAR FENDER SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
3	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
4	REAR DOOR BLACK TAPE <i>new</i> X not nec	1	\$ 60.00	\$ 60.00
5	REAR TYRE <i>new</i>	1	\$ 300.00	\$ 300.00

TOTAL : \$ 530.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	400 400 ✓	
2	SPRAY PAINTING TO AFFECTED AREA rear door + rear fender	\$ 1,000.00	600 400	
3	WIRING CHECK	\$ 100.00	30 30 ✓	
4	TUFF COAT X not nec	\$ 150.00	50	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
6	TO REMOVE UPHOLSTERY TO FACILITATE REPAIRS	\$ 150.00	X	
7	TO REMOVE REAR WINDSCREEN	\$ 180.00	X	
8	TO DISMANTLE REAR UNDERCARRIAGE	\$ 380.00	X	
9	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80 X.	

TOTAL: \$ 3,410.00

ESTIMATE REPORT

TOTAL PARTS COST:	\$	8,054.56
TOTAL LABOUR COST:	\$	3,410.00
TOTAL REPAIR COST:	\$	11,464.56

Total: 366936
1/s: 2.9K
05 Days.

S LC 7081C.

Sin Yn Sin.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: