



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SGK 6259R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	RT FRT HEADLIGHT	SCRATCHED	\$1,100.00	\$1,100.00
1	RT FRT HEADLIGHT HOLDER	NOT NECESSARY	\$82.10	\$0.00
1	RT FRT FENDER COWLING	NOT NECESSARY	\$96.40	\$0.00
1	FRT BUMPER	CRACKED	\$681.00	\$681.00
1	FRT BUMPER REINFORCEMENT	NOT NECESSARY	\$415.20	\$0.00
1	RT FRT BUMPER BRACKET	* CHECK	\$68.00	\$0.00
2	FRT BUMPER SIDE RETAINERS @\$48.20	* CHECK (1PC ONLY)	\$96.40	\$0.00
1	RT FRT FOG LIGHT GARNISH	MISSING	\$115.40	\$115.40
	<b>LESS 20.00% DISCOUNT</b>		(\$530.90)	(\$379.28)
			<b>\$2,123.60</b>	<b>\$1,517.12</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET RT FRT FENDER COWLING CLIPS (SN)	NOT NECESSARY	\$60.00	\$0.00
1	SET FRT BUMPER CLIPS (SN)	NECESSARY	\$72.00	\$30.00
			<b>\$132.00</b>	<b>\$30.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO KNOCK, STRAIGHTEN FRT SUPPORT PANEL, FRT INNER PANEL, FRT LOWER PANEL, FRT SIDE PANEL, RT FRT FENDER, RENEW FRT LIGHT, FRT BUMPER AND ASSEMBLY		\$450.00	\$300.00
	TO RESPRAY DAMAGED PARTS		\$680.00	\$400.00
			<b>\$1,130.00</b>	<b>\$700.00</b>

<b>GRAND TOTAL</b>			<b>\$3,385.60</b>	<b>\$2,247.12</b>
	<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$92.96 NETT)</b>			<b>\$2,247.12</b>

Report Ref No: CS/FCI24100156/Rvp3m4

MARKET VALUE: \$16,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,569.00=NETT VALUE: \$6,431.00

**MRB**

MOHAMMED RASUL BIN MOHD YUNUS



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.