



Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/10/2024

User ID : PohSuan

Section A - Accident Details	
Registration Number	SHB5921D
Case Reference Number	TAX/10/24/2001
Registration Date	26/Dec/2019
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	YAP TECK GIM(YE DEJIN)
Type of Accident	Head to Rear
Accident Date and Time	1/Oct/2024 12:20 PM
Accident Reported Date and Time	1/Oct/2024 4:25 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24100017
Special Instruction to ARC,if any	DAMAGE TO THE FRONT OF TAXI - TP REVERSED TOS TILL 8/10/2024M 10.00 AM/ AIG LKK
Prepared Date and Time	8/Oct/2024 10:25 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$976.00	\$400.00
Total Spare Part Cost	\$5,624.34	\$2,351.22
Total Other Cost	\$380.00	\$60.00
TOTAL COST	\$7,825.34	\$3,111.22
Lump Sum Total	\$7,850.00	\$3,100.00 (L/S)
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK)
ARC / Surveyor Sign Off Date	08/10/2024 9:31 PM	08/10/2024 6:11 PM
Signature		
Remarks	Expected length of repair (days) = 3 days Expected release date of vehicle after repair (Subject to approval from FM and without Supplementary) = 14-10-2024 L/S REPAIR / AFTER PAINT PHOTO, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR TAUFIKH (LKK) / HP : 9749 5749 / Email : taufikh@lkkauto.com	

Section C - Quotation and Accident Invoice Details			
Quotation Number	E24100053	Invoice Number	
Quotation Date	8/10/2024	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$845.00	\$300.00
Total Labour	\$845.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$220.00	\$0.00
Total Spray Painting & Panel Beating	\$976.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$380.00	\$60.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	100.00	\$0.00	Replace	Repair
		52115-47050	SUPPORT, FR BUMPER RH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given
		52161-16010	CLIPS PIECE, FRT BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Not Given
		81145-47890	UNIT, HEADLAMP, RH	1.00	\$2,852.40	25.00	\$2,139.30	Replace	Replace
		81016-47860	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$4,079.80	0.00	\$0.00	Replace	Not Given
		53301-47110	HOOD SUB-ASSY	1.00	\$1,066.30	25.00	\$799.72	Replace	Replace
		53341-47041	INSULATOR, HOOD	0.00	\$444.40	0.00	\$0.00	Replace	Not Given
		90467-09050	INSULATOR, HOOD CLIP	0.00	\$3.10	0.00	\$0.00	Replace	Not Given
		53410-47130	HINGE ASSY, HOOD, RH	0.00	\$63.70	0.00	\$0.00	Replace	Not Given
		53420-47130	HINGE ASSY, HOOD, LH	0.00	\$63.70	0.00	\$0.00	Replace	Not Given
		53213-47050	SUPPORT, RADIATOR UPPER RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given

R  
X  
X  
√ CRA  
X  
√ BT  
X  
X  
X  
X  
X

Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/10/2024  
User ID : PohSuan

Total					\$9,315.20		\$2,939.02		
-------	--	--	--	--	------------	--	------------	--	--

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	2,939.02	
	-20%	L/S \$3,100/-
	2351.22	
+	300.00	
+	460.00	
	3,111.22	