

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

Veron

## ESTIMATE OF REPAIR

Veh# : GBC9559G

Model:

TOYOTA HIACE

Accident Date : 7/7/2024

(16/7/2013 - 15/7/2028)

Location : PAYA LEBAR ROAD

3P:

SNK4841P (INCOME)

| S/Nos. | Qty   | Description                                                                | List \$         | S/Nett \$     | Nett \$    |
|--------|-------|----------------------------------------------------------------------------|-----------------|---------------|------------|
| 1      | 1 pc  | Rear tyre hub cap LH <i>ac u</i>                                           | 288.20          | <i>+</i>      |            |
| 2      | 1 pc  | Sliding door LH <i>Dented</i>                                              | <i>2,860.00</i> | <i>2360</i>   |            |
| 3      | 1 set | Sliding door board clip LH <i>ac u</i>                                     |                 | 50.00         | <i>+</i>   |
| 4      | 1 pc  | Rear fender LH (Repair) <i>2 Repair</i>                                    |                 | <i>+</i>      |            |
| 5      | 1 pc  | Center panel LH (Repair)                                                   |                 | <i>+</i>      |            |
|        |       | <i>2360</i>                                                                | Sub Total:      | 3,148.20      | 50.00      |
|        |       | <i>1770</i>                                                                |                 | 25%           | 0%         |
|        |       |                                                                            | After Less %:   | 2,361.15      | 50.00      |
|        |       |                                                                            |                 |               | 0.00       |
|        |       | <b>Labour</b>                                                              |                 |               |            |
| 1      |       | To remove & refix accident damaged parts & realign accident affected area. |                 | <i>600.00</i> | <i>300</i> |
| 2      |       | To spray paint on accident affected area. <i>990</i>                       |                 | <i>800.00</i> | <i>600</i> |
| 3      |       | To remove & refix door mechanism.                                          |                 | 60.00         | <i>✓</i>   |
| 4      |       | To rust proof affected area.                                               |                 | <i>50.00</i>  | <i>30</i>  |
|        |       | Sub Total:                                                                 |                 | 1,510.00      |            |
|        |       | Total:                                                                     |                 | 3,921.15      |            |

Chan San Choon  
Director  
DipEng, AAE MIMI, MSAE(Aust)

*total 2760 Admin*  
*L/S: 22K L/S 08/10/24*  
*2-2K 03hrs*



**WKK Auto Consultants** hereby certifies the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**8778 1999**  
24 hr accident call

**Mobil 1**