

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

Xiao Chn.

Income Insurance Limited
Income Centre
75 Bras Basah Road Singapore 189557

Attention : Motor Claim Department
Contact : 6788 1777 Fax No. : 6338 1500

Estimate : TP24-128

Date : 04/10/2024
Vehicle Num. : SNK66055
Make/Model : Honda Vezel-2015
Chassis/Eng# : RU11103977/L15B4023979
Accident Date : 03/10/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 pc	Rear Tailgate <i>Dislnd</i>		1,560.80 <i>1100</i>
2.	1 pc	Rear tailgate windscreen moulding <i>new</i>		183.10 <i>✓</i>
3.	1 pc	Rear Tailgate Mechanism Lock <i>Tamed</i>		251.80 <i>✓</i>
4.	1 pc	Rear Tailgate Weatherstrip <i>new</i>		127.00 <i>+</i>
5.	2 pcs	Rear Tailgate Damper L/R <i>new</i>	240.00	480.00 <i>+</i>
6.	1 pc	Rear Tailgate Inner Trim Board <i>new</i>		319.40 <i>✓</i>
7.	2 pcs	Rear tailgate lamp L/R <i>new</i>	492.30	984.60 <i>880</i>
8.	2 pcs	Rear Lamp Assy L/R <i>LH cut</i>	593.50	1,187.00 <i>475</i>
9.	2 pcs	Rear Corner Bumper L/R <i>new</i>	386.70	773.40 <i>386.70</i>
10.	1 pc	Rear Lower Bumper Assy <i>Dislnd</i>		683.70 <i>✓</i>
11.	2 pcs	Rear Bumper Side Holder L/R <i>new</i>	59.80	119.60 <i>+</i>
12.	2 pcs	Rear Bumper Bracket L/R <i>new</i>	39.00	78.00 <i>+</i>
13.	2 pcs	Rear Bumper Reflector Lamp L/R <i>LH cut</i>	184.50	369.00 <i>184.50</i>
14.	1 pc	Rear End Panel <i>Dislnd</i>		758.40 <i>595</i>
15.	1 pc	Rear End Panel Inner Top Garnish <i>Dislnd</i>		179.80 <i>2</i>
16.	1 pc	Rear Tyre Panel <i>Dislnd</i>		983.60 <i>2</i>
17.	1 pc	Rear Exhaust Silencer Box Assy <i>new</i>		759.00 <i>+</i>
18.	1 pc	Rear Exhaust Bush <i>new</i>		39.00 <i>+</i>
19.	2 pcs	Rear Fender Inner Liner L/RH <i>new</i>	297.60	595.20 <i>+</i>
20.	1 pc	Rear Fender Guard LH <i>Dislnd</i>		248.50 <i>✓</i>
21.	1 pc	Rear Tailgate Wiper Motor <i>new</i>		351.20 <i>+</i>
22.	1 pc	Rear Tailgate Vezel Emblem <i>new</i>		68.10 <i>✓</i>
23.	1 pc	Rear Tailgate Honda Logo <i>new</i>		57.40 <i>+</i>
24.	1 pc	Rear Tailgate No Plate Lamp Garnish <i>new</i>		89.10 <i>2</i>
25.	1 pc	Rear Tyre Panel Inner Top Trim Board <i>Dislnd</i>		328.70 <i>2</i>
26.	1 pc	Rear Tyre Panel Inner Tools Sponge <i>new</i>		239.10 <i>2</i>
27.	1 pc	Rear Tyre Panel Lower Under Trim Board <i>Dislnd</i>		323.90 <i>2</i>
28.	1 pc	Rear Exhaust Centre Mid Pipe <i>new</i>		631.60 <i>+</i>
29.	1 pc	Frt Bumper Assy <i>Dislnd</i>		948.50 <i>765</i>

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

Income Insurance Limited
Income Centre
75 Bras Basah Road Singapore 189557

Attention : Motor Claim Department
Contact : 6788 1777 Fax No. : 6338 1500

Estimate : TP24-128

Date : 04/10/2024
Vehicle Num. : SNK66055
Make/Model : Honda Vezel-2015
Chassis/Eng# : RU11103977/L15B4023979
Accident Date : 03/10/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	2 pcs	Frt Bumper Side Holder L/R <i>den</i>	52.00	104.00 +
31.	1 pc	Frt Lower Bumper Extension <i>den</i>		424.30 +
32.	1 pc	Frt Bumper Lower Air Grille <i>den</i>		156.40 +
33.	1 pc	Frt Grille Assy <i>could</i>		423.50 ✓
34.	1 pc	Frt Grille Base <i>could</i>		380.50 ✓
35.	1 pc	Frt Grille Chrome <i>could</i>		81.40 ✓
36.	1 pc	Frt honda logo <i>new</i>		57.20 ✓
37.	1 pc	Frt Bumper Inner Reinforcement <i>Dented</i>		421.00 ✓
38.	2 pcs	Frt Headlamp Assy L/R <i>Both side LH could</i>	1,380.60	2,761.20 1380.60
39.	1 pc	Frt Bonnet <i>Dented</i>		874.50 ✓
40.	1 pc	Frt Bonnet Lock <i>den</i>		158.50 X
41.	1 pc	Aircon Condenser <i>new</i>		768.50 F
42.	1 pc	Frt Support Panel <i>new</i>		675.91 305
43.	2 pcs	Rear Fender Inner Trim Board L/R <i>could</i>	498.10	996.20 A.
44.	1 pc	Frt Bonnet Lock Bracket <i>new</i>		78.40
List TotalS\$:				22,080.01
20.00% Discount S\$:				4,416.00
				17,664.01
SPECIAL NETT ITEMS :				
1.	10 pcs	Rear Bumper Clips <i>new</i>	4.60	46.00 30
2.	1 pc	Rear Reverse Sensor <i>new</i>		280.00 20
3.	10 pcs	Frt Bumper Clips <i>new</i>	4.50	45.00 30.
4.	1 pc	Rear number plate with frame <i>new</i>		45.00 +
5.	1 pc	Frt No. Plate with Frame <i>could</i>		45.00 ✓
6.	1 set	Rear Tyre Panel Lower Under Trim Board Clips <i>new</i>		30.00 ✓
Special Nett Total S\$:				491.00
LABOUR :				
To remove, repair and replaced damaged bodyparts,				2,800.00

CONTINUE / ...

1500
1200
1500

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub. Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

Income Insurance Limited
 Income Centre
 75 Bras Basah Road Singapore 189557

Attention : Motor Claim Department
 Contact : 6788 1777 Fax No. : 6338 1500

Estimate : TP24-128

Date : 04/10/2024
 Vehicle Num. : SNK6605S
 Make/Model : Honda Vezel-2015
 Chassis/Eng# : RU11103977/L15B4023979
 Accident Date : 03/10/2024
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		realign bodyworks & where consistent to the accident		
		To remove, rearrange electrical wirings, check lighting		150.00 60
		To remove, instal rear windscreen		280.00 120
		To remove, replace rear tailgate to transfer gear, motor and components.		250.00 60
		To remove, instal inner trim, seat, garnishes etc.		250.00 60
		To remove, install aircon parts, vacuum, renew gas.		250.00 +
		To remove, replace rear exhaust to facilitate repair and align pipe line.	3000	200.00 +
		To putty and respray painting on frt bonnet, bumper, support panel, reinforcement, rear tailgate, rear bumper, rear end panel and rear tyre panel.		2,200.00 120
		Labour Total S\$:		6,380.00

Adnan L
 1/s 08/10/24.
 10 Days.

Total S\$: 24,535.01
 =====

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

total: 1300660
 1/s: 10.4K