

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internat	ionale Des Experts En	Automobile		
MS	LIBERTY INSURANCE PTE LTD		Ref:	CS/LIP24100163/Uqh3e2		
		JAY #25-01 NORTH TOWER 83	Date:	30/10/2024		
	SINGAPORE 0485		Code:	LIP		
1.	Policy Particulars :- THIRD PARTY CLAIM (PHYSICAL REINSPECTION)					
	Insured Veh.	SGZ 6367H	Veh. Inspected	SFD 555Z		
	Policy No.	-	Coverage	0		
	Claim No.	AVS24/2525	Excess	\$0.00		
	Assign From	STEWART LIM	Assign Date	08/10/2024		
2.	Vehicle Details					
	Make & Model	B.M.W. 116D (A)	C.C	1496		
	Engine No.	37539812B37D15A	Year of Reg.	27/02/2017		
	Chassis No.	WBA1V720305G86422	Colour	GREY		
	Odometer	120103 KM	Steering	IN ORDER		
	Brakes	IN ORDER	General	GOOD		
	Modification(s)	RIMS: SPORTS RIM				
3.	Conditions of Tyres					
		Size	Make	Balance (mm)		
	R/H Front Tyre	225/40R18	PAPIDE	4		
	L/H Front Tyre	225/40R18	PAPIDE	4		
	R/H Rear Tyre	225/40R18	PAPIDE	4		
	L/H Rear Tyre	225/40R18	PAPIDE	4		
4. Description of Damages						
THE	VEHICLE HAD CC	MPLETED ITS REPAIR WORKS.				
REF	PAIR CONDITION S	EE DETAILS.				
5.						
	Accident Date	14/08/2024	Inspection Date	25/10/2024		
	Survey held at	TOPMAX AUTO BODYSHOP - BLK 3007 UBI ROAD 1 #01-410 . SINGAPORE 408701				
		5a. Remarks				
A) T		/AS CONDUCTED ON A"WITHOUT O YOUR INSTRUCTIONS, WE HAV		REPAIRS.		

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days