	CINCAPORE 417992 TEL 67452099	No illegal modification(s) is allowed
	SINGAPORE 417883 TEL :67452088 9((3)) 4	 Supplementary item(s) must be resurveded mile
	1/5 th 4800	is subject to final approval from Insurance Company
	The shorts Affer repair	Acknowledged by Repairer
	VEHICLE NO: SJK 2113T Who photo Affer repair 6 days.	Signature:
		Date:
1PC	REAR WINDSCREEN MOULDING 18C	\$80.60
1PC	TAILGATE BOOK OD	fre. 20 \$932.90
1PC	TAILGATE 'JAZZ' EMBLEM	\$32.00
1PC	TAILGATE INNER LOCK Ruffyn	\$223.80
1PC	TAILGATE INNER LOCK CABLE SW	\$110.20
1PC	TAILGATE WEATHERSTRIP 1M	\$108.30
1PC	TAILGATE INNER TRIM BOARD Se CO.	\$264.80
1PC	TAILGATE OUTER CHROME MOULDING 1	\$238.20 🗴
1PC	REAR BUMPER >>>	\$524.20
2PCS	RAER BUMPER SIDE RETAINERS @\$25.00	\$50.00 🗡
2PCS	REAR BUMPER LOWER SIDE BLACK GARNISHS @\$62.80 YW	\$125.60
1PC	REAR END PANEL 170 /344	\$380.50
1PC	REAR END PANEL TOP GARNISH 1~1	\$120.90
2PCS	TAILLAMPS @\$309.50	\$619.00
2PCS	TAILLAMP HOUSING PANELS @\$180.00 /_	\$360.00 🗸
1PC	REAR FLOOR PANEL	\$737.00 🗸
1PC	REAR FLOOR PANEL TOP BOARD word	\$216.00
1PC	REAR FLOOR PANEL TOOLS SPONGE TOIA	\$345.20
1PC	REAR FENDER INNER TRIM O/S Pul Torn	\$288.30
1PC		\$971.20 💢
1PC	REAR FENDER N/S RAER FENDER O/S	\$971.20 %
1PC	REAR BUZZER SENSOR	\$100.80
110	REAR BOLLER SERIOUR	\$7,800.70
		LESS 20% \$6,240.56
	S.NETT	
1PC	REAR WINDSCREEN SEALANT	\$40.00 ~ 5/N
1PC	REAR WINDSCREEN INNER SEAL 1M	\$30.00
1SET	REAR BUMPER CLIPS	\$30.00 /
1SET	TAILGATE INNER TRIM BOARD CLIPS 124	\$30.00
1PC	REAR END PANEL SEALANT	\$50.00
1SET	REAR BUMPER REVERSE SENSOR 4 PCS Molfudor	\$320.00 200
	TO CHECK WIRING	\$50.00 -20
	TO DISMANTLE & REFIX REAR WINDSCREEN	\$120.00
	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00 30
	TO DISMANTLE & REFIX REAR REVERSE CAMERA	ハヘ \$100.00 X
	TO DISMANTLE & REFIX REAR TAILGATE MECHANISM	\$100.00 60
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00 6 2
	TO SPRAY RUST PROOFING	\$100.00 60
	TO DIAGNOSTIC & REPROGRAMME SYSTEM	مم \$250.00 X
	LABOUR FOR PANEL BEATING	\$1,100.00 800
	TO PUTTY & SPRAY PAINTING	\$1,580.00 /080
	٩- 4)142	
	202	701AL \$ 10340:56
	3020	

280

BLUWEL AUTOMOTIVE SERVICE PTE LTD Not Arthorist

Morcus

1 KAKI BUKIT AVE 6 # 01-28/53/55/56

LKK Auto Consultants hence notify the Repairer of the following:

• To recurvey before/after spray pointing

• To display damaged partic, it is a resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudios" bactu